












CARFAX® Vehicle History Report™




An independent company established in 1986

US \$39.99




<p>Vehicle Information: 2011 SUBARU OUTBACK 2.5I PREMIUM VIN: 4S4BRBCC3B3412488 4 DOOR WAGON/SPORT UTILITY 2.5L H4 F DOHC 16V GASOLINE ALL WHEEL DRIVE Standard Equipment Safety Options</p> <p>CARFAX Report Provided By: Van Bortel Ford 71 Marsh Rd East Rochester, NY 14445 833-205-1341 www.vanbortelford.com</p> <p>4.7 ★★★★★ 22 Verified Reviews</p>	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center; width: 40px;"></td> <td>No accidents reported to CARFAX</td> </tr> <tr> <td style="text-align: center;"></td> <td>No damage reported to CARFAX</td> </tr> <tr> <td style="text-align: center;"></td> <td>CARFAX 1-Owner vehicle</td> </tr> <tr> <td style="text-align: center;"></td> <td>At least 1 open recall</td> </tr> <tr> <td style="text-align: center;"></td> <td>7 Service history records</td> </tr> <tr> <td style="text-align: center;"></td> <td>83,696 Last reported odometer reading</td> </tr> </table>		No accidents reported to CARFAX		No damage reported to CARFAX		CARFAX 1-Owner vehicle		At least 1 open recall		7 Service history records		83,696 Last reported odometer reading
	No accidents reported to CARFAX												
	No damage reported to CARFAX												
	CARFAX 1-Owner vehicle												
	At least 1 open recall												
	7 Service history records												
	83,696 Last reported odometer reading												



This CARFAX Vehicle History Report is based only on [information](#) supplied to CARFAX and available as of 6/4/19 at 6:53:07 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

 Ownership History		 Owner 1
The number of owners is estimated		
Year purchased		2011
Type of owner		Personal
Estimated length of ownership		7 yrs. 11 mo.
Owned in the following states/provinces		Massachusetts, New York
Estimated miles driven per year		10,894/yr
Last reported odometer reading		83,696

 Title History		 Owner 1
CARFAX guarantees the information in this section		
Salvage Junk Rebuilt Fire Flood Hail Lemon		Guaranteed No Problem
Not Actual Mileage Exceeds Mechanical Limits		Guaranteed No Problem
 <p style="margin: 0; font-size: small;"> GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. Register View Terms View Certificate </p>		


 Additional History		 Owner 1
Not all accidents / issues are reported to CARFAX		
Total Loss No total loss reported to CARFAX.		 No Issues Reported

Structural Damage No structural damage reported to CARFAX.	No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	No Issues Reported
Odometer Check No indication of an odometer rollback.	No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	No Issues Reported
Manufacturer Recall At least 1 manufacturer recall requires repair. Most recalls can be repaired free of charge.	Recall Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired



Detailed History

Glossary

<p>Owner 1</p> <p>Purchased: 2011 Type: Personal Where: Massachusetts, New York Est. miles/year: 10,894/yr Est. length owned: 5/21/11 - 5/15/19 (7 yrs. 11 mo.)</p> <p>Low mileage! This owner drove less than the industry average of 15,000 miles per year.</p> 	Date:	Mileage:	Source:	Comments:
	04/29/2011	3	TriCity Subaru Somersworth, NH 603-742-3647 tricitysubaru.com 4.6 ★★★★★ 52 Verified Reviews	Pre-delivery inspection completed Vehicle washed/detailed
	05/02/2011	10	TriCity Subaru Somersworth, NH 603-742-3647 tricitysubaru.com 4.6 ★★★★★ 52 Verified Reviews	Vehicle offered for sale
	05/06/2011		Subaru of North Reading North Reading, MA 978-396-6090 northreadingsubaru.com 4.6 ★★★★★ 49 Verified Reviews	Vehicle offered for sale
	05/21/2011	30	Balise Auto Group baliseauto.com	Vehicle sold
	05/21/2011		Balise Subaru of Warwick Warwick, RI 401-780-3490 baliseauto.com	Vehicle washed/detailed
	05/21/2011		Massachusetts Motor Vehicle Dept.	Vehicle purchase reported Titled or registered as personal vehicle
	06/02/2011		Massachusetts Motor Vehicle Dept. Westport, MA	Registration issued or renewed Vehicle color noted as Red
	06/08/2011	100	Massachusetts Inspection Station Westport, MA	Passed safety inspection
	06/17/2011	170	Massachusetts Motor Vehicle Dept. Westport, MA Title #BK168843	Title issued or updated First owner reported Vehicle color noted as Red

07/09/2011	2,521	Balise Subaru of Warwick Warwick, RI 401-780-3490 baliseauto.com	Maintenance inspection completed
06/21/2012	15,721	Massachusetts Inspection Station Westport, MA	Passed safety inspection Passed emissions inspection
07/01/2012		Massachusetts Motor Vehicle Dept. Westport, MA Title #BK168843	Registration issued or renewed Registration updated when owner moved the vehicle to a new location Vehicle color noted as Red
12/18/2012		New York Motor Vehicle Dept. Marcellus, NY	Registration issued or renewed Titled or registered as personal vehicle Passed safety inspection Registration updated when owner moved the vehicle to a new location
02/21/2013		New York Motor Vehicle Dept. Marcellus, NY	Title issued or updated
06/19/2013	27,985	New York Inspection Station	Passed safety inspection Passed emissions inspection View what was inspected
06/25/2013		Wirth's Automotive Inc Skaneateles, NY 315-685-2700 wirthsautomotiveinc.com	Safety inspection performed Emissions inspection performed
06/20/2014	40,970	Wirth's Automotive Inc Skaneateles, NY 315-685-2700 wirthsautomotiveinc.com	Safety inspection performed Emissions inspection performed
06/20/2014		New York Inspection Station	Passed safety inspection Emissions inspection performed View what was inspected
10/29/2014		New York Motor Vehicle Dept. Marcellus, NY	Registration issued or renewed Titled or registered as personal vehicle Passed safety inspection
07/02/2015	52,665	Wirth's Automotive Inc Skaneateles, NY 315-685-2700 wirthsautomotiveinc.com	Lights checked Safety inspection performed Emissions inspection performed
07/02/2015		New York Inspection Station	Passed safety inspection Passed emissions inspection View what was inspected
09/12/2016	63,671	Wirth's Automotive Inc Skaneateles, NY 315-685-2700 wirthsautomotiveinc.com	Safety inspection performed Emissions inspection performed
09/12/2016		New York Inspection Station	Passed safety inspection Passed emissions inspection View what was inspected

09/23/2016	Subaru of America	Manufacturer Safety recall issued NHTSA #16V694000 Recall #WTK71 2010-2014 LEGACY/OUTBACK WINDSHIELD WIPER MOTOR Status: Remedy Available
------------	-------------------	--

[Click Here](#) or email us at customers@subaru.com to locate an authorized Subaru dealership near you to obtain more information about this recall.

- [Learn more about this recall](#)

Description: Subaru of America, Inc. (Subaru) is recalling certain model year 2010-2014 Legacy vehicles manufactured November 26, 2008, to June 7, 2013, and 2010-2014 Outback vehicles manufactured January 9, 2009 to June 7, 2013. Due to contamination, components within the windshield wiper motor bottom cover may interfere with each other. If an obstruction, such as a buildup of snow or ice prevents the wiper arms from being able to stop in the parked position, the wiper motor may overheat and the bottom cover may melt.

If the windshield wiper motor overheats, the wipers may fail, reducing driver visibility and increasing the risk of a crash. Additionally, the wiper motor cover may melt, increasing the risk of a fire.

Remedy: Subaru will notify owners, and dealers will replace the windshield wiper motor bottom cover assembly, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Subaru customer service at 1-800-782-2783. Subaru's number for this recall is WTK-71. Note: This recall supersedes recall 11V-469. All vehicles that were remedied under that campaign are affected by this campaign, and need to have their wiper motor bottom cover replaced again. NOTES: Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

10/31/2016	New York Motor Vehicle Dept. Marcellus, NY	Registration issued or renewed Titled or registered as personal vehicle Passed safety inspection	
09/23/2017	72,532	New York Inspection Station	Passed safety inspection Passed emissions inspection
View what was inspected			
10/25/2018	New York Motor Vehicle Dept. Marcellus, NY	Registration issued or renewed Titled or registered as personal vehicle Passed safety inspection	
01/09/2019	Subaru of America	Manufacturer Safety recall issued NHTSA #19V009000 Recall #TKC19 10-14 LEG&OUT TAKATA AB INFLATOR RECALL EXPANSION Status: Remedy Available	
<p>Click Here or email us at customers@subaru.com to locate an authorized Subaru dealership near you to obtain more information about this recall.</p>			

[- Learn more about this recall](#)

Description: Subaru of America, Inc. (Subaru) is recalling certain 2010-2014 Legacy, Tribeca, WRX and Outback vehicles, 2010-2013 Forester vehicles and 2010-2011 Impreza vehicles sold, or ever registered, in the states of Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, and Wyoming. These vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

An explosion of an inflator within the passenger frontal air bag module may result in sharp metal fragments striking the front seat passenger, driver or other occupants resulting in serious injury or death.

Remedy: Subaru will notify owners, and dealers will replace the front passenger air bag inflator, free of charge. Owners may contact Subaru customer service at 1-844-373-6614. Subaru's number for this recall is TKC-19. Notes: Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

01/23/2019	83,696	New York Inspection Station	Passed safety inspection Passed emissions inspection View what was inspected
05/15/2019		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Vehicle offered for sale

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

[View Full Glossary](#)

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform owners of car defects that have come to the manufacturer's attention. Recalls also suggest improvements that can be made to improve the safety of a particular vehicle. Most manufacturer recalls can be repaired at no cost to you.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us: [facebook.com/CARFAX](https://www.facebook.com/CARFAX) [@CarfaxReports](https://twitter.com/CarfaxReports)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX

FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. CARFAX®

© 2019 CARFAX, Inc., a unit of IHS Markit. All rights reserved.

Covered by United States Patent Nos. 7,113,853; 7,778,841; 7,596,512, 8,600,823; 8,595,079; 8,606,648; 7,505,838.

6/4/19 6:53:07 AM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2011 SUBARU OUTBACK vehicle (VIN: 4S4BRBCC3B3412488), which is based on information supplied to CARFAX and available as of 6/4/19 at 7:53 AM (EDT).

Customer Signature

Date

Dealer Signature

Date