


Display CARFAX in online listings:




This report provided free of charge by:

**Van Bortel Ford**  
 71 Marsh Rd  
 East Rochester, NY 14445  
 585-460-1438

**2022 TOP RATED DEALER**






★ **4.8 / 5.0**  
 1,284 Verified Reviews

♥ **9,217**  
 Customer Favorites





## Vehicle History Report™

US \$44.99

<p><b>2012 SUBARU OUTBACK 2.5I PREMIUM</b></p> <p>VIN: 4S4BRBGC3C3232634              4 DOOR WAGON/SPORT              UTILITY              2.5L H4 F DOHC 16V              GASOLINE              ALL WHEEL DRIVE              This CARFAX Report Provided              by:  <b>Van Bortel Ford</b>              ★ <b>4.8 / 5.0</b>              1,284 Verified Reviews              ♥ <b>9,217</b> Customer Favorites</p>	<p><b>Accident reported: minor to moderate damage</b></p> <div style="display: flex; align-items: center;">  <div style="flex-grow: 1;"> <div style="border: 1px solid black; width: 100%; height: 15px; position: relative;"> <div style="background-color: #ccc; width: 40%;"></div> <div style="background-color: #007bff; width: 20%; position: absolute; left: 40%;"></div> </div> <div style="display: flex; justify-content: space-between; font-size: 0.8em; margin-top: 5px;"> <span>MINOR</span> <span>MODERATE</span> <span>SEVERE</span> </div> </div> </div>
	<p> Regular oil changes</p>
	<p> CARFAX 1-Owner vehicle</p>
	<p> Personal vehicle</p>
	<p> <b>126,350</b> Last reported odometer reading</p>

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 9/10/23 at 10:00:56 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

 <b>Ownership History</b> The number of owners is estimated	<b>Owner 1</b>
Year purchased	2012
Type of owner	Personal
Estimated length of ownership	11 yrs. 8 mo.
Owned in the following states/provinces	New York
Estimated miles driven per year	10,876/yr
	126,350



Last reported odometer reading



### Title History

CARFAX guarantees the information in this section

Owner 1

#### Damage Brands

Salvage | Junk | Rebuilt | Fire | Flood | Hail | Lemon

**Guaranteed**  
No Problem

#### Odometer Brands

Not Actual Mileage | Exceeds Mechanical Limits

**Guaranteed**  
No Problem



**GUARANTEED** - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back.  
[View Terms](#) | [View Certificate](#)



### Additional History

Not all accidents / issues are reported to CARFAX

Owner 1

#### Total Loss

No total loss reported to CARFAX.

No Issues  
Reported

#### Structural Damage

CARFAX recommends that you have this vehicle inspected by a collision repair specialist.

No Issues  
Reported

#### Airbag Deployment

No airbag deployment reported to CARFAX.

No Issues  
Reported

#### Odometer Check

No indication of an odometer rollback.

No Issues  
Indicated

#### Accident / Damage

Accident reported: 11/06/2022.

Accident Reported

#### Manufacturer Recall

Check with an authorized Subaru dealer for any open recalls.

No Recalls  
Reported

#### Basic Warranty

Original warranty estimated to have expired.

Warranty Expired



### Detailed History



**Owner 1**

Purchased: 2012



**Low mileage!** This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle  
10,876 mi/yr

Date

Mileage

Source

Comments

12/15/2011

Van Bortel Subaru  
Victor, NY

Vehicle offered for sale

585-924-5230  
vanbortelsubaru.com  
★ 4.8 / 5.0  
146 Verified Reviews  
♥ 11 Customer Favorites

12/15/2011 6

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com  
★ 4.8 / 5.0  
146 Verified Reviews  
♥ 11 Customer Favorites



**Vehicle serviced**

- Pre-delivery inspection completed

01/02/2012 7

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com  
★ 4.8 / 5.0  
146 Verified Reviews  
♥ 11 Customer Favorites



**Vehicle serviced**

- Safety inspection performed  
- Emissions or safety inspection performed

01/02/2012

New York  
Inspection Station

**Passed safety inspection**

- Emissions inspection performed

01/05/2012

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com  
★ 4.8 / 5.0  
146 Verified Reviews  
♥ 11 Customer Favorites

**Vehicle sold**

01/05/2012

New York  
Motor Vehicle Dept.  
Rochester, NY

**Registration issued or renewed**

- Titled or registered as personal vehicle  
- Passed safety inspection

01/19/2012 476

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com  
★ 4.8 / 5.0  
146 Verified Reviews  
♥ 11 Customer Favorites



**Vehicle serviced**

02/01/2012

New York  
Motor Vehicle Dept.  
Rochester, NY

**Title issued or updated**

- First owner reported  
- Titled or registered as personal vehicle  
- Loan or lien reported

03/28/2012 3,299

Van Bortel Subaru  
Victor, NY



**Vehicle serviced**

- Oil and filter changed

585-924-5230  
vanbortelsubaru.com

★ 4.8 / 5.0

146 Verified Reviews

♥ 11 Customer Favorites

05/15/2012 6,759

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

- 7,500 mile service performed
- Oil and filter changed
- Tire condition and pressure checked

★ 4.8 / 5.0

146 Verified Reviews

♥ 11 Customer Favorites

07/03/2012 10,229

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

- Oil and filter changed

★ 4.8 / 5.0

146 Verified Reviews

♥ 11 Customer Favorites

08/03/2012 13,344

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

- Oil and filter changed

★ 4.8 / 5.0

146 Verified Reviews

♥ 11 Customer Favorites

11/01/2012 16,450

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

- Oil and filter changed
- Tire condition and pressure checked

★ 4.8 / 5.0

146 Verified Reviews

♥ 11 Customer Favorites

11/27/2012 19,020

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

- Cabin air filter replaced/cleaned
- Oil and filter changed
- Engine/powertrain computer/module reprogrammed

★ 4.8 / 5.0

146 Verified Reviews

♥ 11 Customer Favorites

01/22/2013 20,473


Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

























**Vehicle serviced**

- Emissions or safety inspection performed

★ 4.8 / 5.0

146 Verified Reviews  
 11 Customer Favorites

01/22/2013		New York Inspection Station	<b>Passed safety inspection</b> - Emissions inspection performed
02/22/2013	22,432	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  <b>4.8 / 5.0</b> 146 Verified Reviews  11 Customer Favorites	 <b>Vehicle serviced</b> - 7,500 mile service performed - Oil and filter changed
05/16/2013	25,675	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  <b>4.8 / 5.0</b> 146 Verified Reviews  11 Customer Favorites	 <b>Vehicle serviced</b> - Oil and filter changed
06/20/2013	28,527	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  <b>4.8 / 5.0</b> 146 Verified Reviews  11 Customer Favorites	 <b>Vehicle serviced</b> - Oil and filter changed
08/02/2013	31,609	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  <b>4.8 / 5.0</b> 146 Verified Reviews  11 Customer Favorites	 <b>Vehicle serviced</b> - Recommended maintenance performed - 30,000 mile service performed - Oil and filter changed - Tires rotated
10/27/2013		New York Motor Vehicle Dept. Rochester, NY	<b>Registration issued or renewed</b> - Titled or registered as personal vehicle - Passed safety inspection
10/30/2013	34,660	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  <b>4.8 / 5.0</b> 146 Verified Reviews  11 Customer Favorites	 <b>Vehicle serviced</b> - Oil and filter changed
01/24/2014	37,024	Sears Auto Center Rochester, NY	 <b>Vehicle serviced</b>

		585-475-8228 searsauto.com ★ 4.6 / 5.0 47 Verified Reviews		- Emissions or safety inspection performed
01/24/2014		New York Inspection Station		<b>Passed safety inspection</b> - Emissions inspection performed
02/13/2014	37,517	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 146 Verified Reviews ♥ 11 Customer Favorites		<b>Vehicle serviced</b>
03/12/2014	38,345	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 146 Verified Reviews ♥ 11 Customer Favorites		<b>Vehicle serviced</b> - Oil and filter changed
06/16/2014	42,251	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 146 Verified Reviews ♥ 11 Customer Favorites		<b>Vehicle serviced</b> - Oil and filter changed
10/22/2014	46,237	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 146 Verified Reviews ♥ 11 Customer Favorites		<b>Vehicle serviced</b> - 15,000 mile service performed - Oil and filter changed
01/21/2015	48,394	Sears Auto Center Rochester, NY 585-475-8228 searsauto.com ★ 4.6 / 5.0 47 Verified Reviews		<b>Vehicle serviced</b> - Emissions or safety inspection performed
01/21/2015		New York Inspection Station		<b>Passed safety inspection</b> - Passed emissions inspection
03/05/2015	50,101	Van Bortel Subaru Victor, NY		<b>Vehicle serviced</b> - Oil and filter changed

585-924-5230  
vanbortelsubaru.com

★ 4.8 / 5.0

146 Verified Reviews

♥ 11 Customer Favorites

06/12/2015 52,418

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

★ 4.8 / 5.0

146 Verified Reviews

♥ 11 Customer Favorites

09/02/2015 54,155

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

- Oil and filter changed

★ 4.8 / 5.0

146 Verified Reviews

♥ 11 Customer Favorites

11/11/2015

New York  
Motor Vehicle Dept.  
Rochester, NY

**Registration issued or renewed**

- Titled or registered as personal vehicle  
- Passed safety inspection

01/14/2016 57,835

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

- Oil and filter changed  
- Safety inspection performed  
- Two tires balanced  
- Tires rotated  
- Emissions inspection performed

★ 4.8 / 5.0

146 Verified Reviews

♥ 11 Customer Favorites

01/14/2016 57,836

New York  
Inspection Station

**Passed safety inspection**

- Passed emissions inspection

06/15/2016 61,614

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

- 60,000 mile service performed  
- Rear brake pads replaced  
- Rear brake rotor(s) replaced  
- Brake rotor(s) replaced  
- Air filter replaced

★ 4.8 / 5.0

146 Verified Reviews

♥ 11 Customer Favorites

07/11/2016 62,378


Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

★ 4.8 / 5.0

146 Verified Reviews


 11 Customer Favorites

07/25/2016 62,715

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

 4.8 / 5.0

146 Verified Reviews

 11 Customer Favorites




**Vehicle serviced**

08/19/2016 63,767

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

 4.8 / 5.0

146 Verified Reviews

 11 Customer Favorites



**Vehicle serviced**


- Maintenance inspection completed
- Oil and filter changed
- Tire condition and pressure checked
- Wipers/washers checked

09/08/2016 64,266

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

 4.8 / 5.0

146 Verified Reviews

 11 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed
- Oil and filter changed
- Tire condition and pressure checked
- Wipers/washers checked

12/06/2016 66,253

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

 4.8 / 5.0

146 Verified Reviews

 11 Customer Favorites



**Vehicle serviced**

01/30/2017 67,102

New York  
Inspection Station

**Passed safety inspection**


- Passed emissions inspection

03/08/2017 67,996

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

 4.8 / 5.0

146 Verified Reviews

 11 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed
- Cabin air filter replaced/cleaned
- Oil and filter changed
- Tire condition and pressure checked
- Wipers/washers checked

06/21/2017 71,488

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

 4.8 / 5.0


146 Verified Reviews



**Vehicle serviced**

- Maintenance inspection completed
- Air filter replaced
- Tire condition and pressure checked




 11 Customer Favorites

08/21/2017 72,822

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

 4.8 / 5.0

146 Verified Reviews

 11 Customer Favorites



**Vehicle serviced**

- Brake light bulb(s) replaced

10/05/2017 74,180

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

 4.8 / 5.0

146 Verified Reviews

 11 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed  
- Oil and filter changed  
- Tire condition and pressure checked  
- Wipers/washers checked

10/19/2017

New York  
Motor Vehicle Dept.  
Rochester, NY

**Registration issued or renewed**


- Titled or registered as personal vehicle  
- Passed safety inspection

11/28/2017 75,724

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

 4.8 / 5.0

146 Verified Reviews

 11 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed  
- Brakes checked

01/24/2018

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

 4.8 / 5.0

146 Verified Reviews

 11 Customer Favorites



**Vehicle serviced**

01/24/2018 76,815

New York  
Inspection Station

**Passed safety inspection**

- Passed emissions inspection

02/28/2018 77,777

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

 4.8 / 5.0

146 Verified Reviews

 11 Customer Favorites



**Vehicle serviced**

- Oil and filter changed  
- Front brake rotor(s) replaced  
- Front brake pads replaced  
- Brake rotor(s) replaced

04/16/2018 81,522

Van Bortel Subaru  
Victor, NY  
585-924-5230



**Vehicle serviced**

- Oil and filter changed

vanbortelsubaru.com

★ 4.8 / 5.0

146 Verified Reviews

♥ 11 Customer Favorites

06/27/2018 84,286

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

★ 4.8 / 5.0

146 Verified Reviews

♥ 11 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed
- Oil and filter changed

09/18/2018 87,277

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

★ 4.8 / 5.0

146 Verified Reviews

♥ 11 Customer Favorites



**Vehicle serviced**

- Cabin air filter replaced/cleaned
- Oil and filter changed
- Four tires balanced
- Tires rotated

11/21/2018 89,122

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

★ 4.8 / 5.0

146 Verified Reviews

♥ 11 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed

01/07/2019 89,733

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

★ 4.8 / 5.0

146 Verified Reviews

♥ 11 Customer Favorites



**Vehicle serviced**

01/16/2019 89,979

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

★ 4.8 / 5.0

146 Verified Reviews

♥ 11 Customer Favorites



**Vehicle serviced**

- Emissions or safety inspection performed

01/16/2019

New York  
Inspection Station

**Passed safety inspection**

- Passed emissions inspection

02/16/2019 90,373

Van Bortel Subaru  
Victor, NY  
585-924-5230



**Vehicle serviced**

- License plate light bulb(s) replaced

vanbortelsubaru.com

★ 4.8 / 5.0

146 Verified Reviews

♥ 11 Customer Favorites

03/05/2019 90,862

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

- 90,000 mile service performed
- Battery/charging system checked
- Air filter replaced

★ 4.8 / 5.0

146 Verified Reviews

♥ 11 Customer Favorites

05/31/2019 93,940

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

- Maintenance inspection completed
- Oil and filter changed

★ 4.8 / 5.0

146 Verified Reviews

♥ 11 Customer Favorites

08/13/2019 97,028

Van Bortel Subaru Of  
Rochester  
Rochester, NY  
888-309-5502  
vanbortelsubarurocheste  
rsoa.dealer.subaru.com/



**Vehicle serviced**

- Maintenance inspection completed
- Cabin air filter replaced/cleaned
- Oil and filter changed

★ 4.7 / 5.0

105 Verified Reviews

♥ 11 Customer Favorites

10/22/2019

New York  
Motor Vehicle Dept.  
Rochester, NY

**Registration issued or renewed**

- Titled or registered as personal vehicle
- Passed safety inspection

01/08/2020 100,439

Van Bortel Subaru Of  
Rochester  
Rochester, NY  
888-309-5502  
vanbortelsubarurocheste  
rsoa.dealer.subaru.com/



**Vehicle serviced**

- Inspection performed
- Tire checked
- Maintenance inspection completed
- Oil and filter changed
- Emissions or safety inspection performed

★ 4.7 / 5.0

105 Verified Reviews

♥ 11 Customer Favorites

01/08/2020

New York  
Inspection Station

**Passed safety inspection**

- Passed emissions inspection

07/03/2020 102,505

Van Bortel Subaru Of  
Rochester  
Rochester, NY  
888-309-5502



**Vehicle serviced**

- Inspection performed
- Tire checked
- Maintenance inspection completed

vanbortelsubarurocheste  
rsoa.dealer.subaru.com/

★ 4.7 / 5.0

105 Verified Reviews

♥ 11 Customer Favorites

- Tire repaired

07/22/2020 102,868

Van Bortel Subaru Of  
Rochester  
Rochester, NY  
888-309-5502  
vanbortelsubarurocheste  
rsoa.dealer.subaru.com/

★ 4.7 / 5.0

105 Verified Reviews

♥ 11 Customer Favorites



**Vehicle serviced**

- Inspection performed
- Tire checked
- Maintenance inspection completed
- Oil and filter changed
- Rear brake pads replaced
- Rear brake rotor(s) replaced

09/02/2020 104,003

Van Bortel Subaru Of  
Rochester  
Rochester, NY  
888-309-5502  
vanbortelsubarurocheste  
rsoa.dealer.subaru.com/

★ 4.7 / 5.0

105 Verified Reviews

♥ 11 Customer Favorites



**Vehicle serviced**

- Inspection performed
- Tire checked
- Maintenance inspection completed
- Headlight bulb(s) replaced
- Rear wiper blade replaced

09/30/2020 104,943

Van Bortel Subaru Of  
Rochester  
Rochester, NY  
888-309-5502  
vanbortelsubarurocheste  
rsoa.dealer.subaru.com/

★ 4.7 / 5.0

105 Verified Reviews

♥ 11 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed
- Brake fluid flushed/changed
- Cabin air filter replaced/cleaned
- Air filter replaced
- Light bulb(s) replaced

11/27/2020 106,297

Van Bortel Subaru Of  
Rochester  
Rochester, NY  
888-309-5502  
vanbortelsubarurocheste  
rsoa.dealer.subaru.com/

★ 4.7 / 5.0

105 Verified Reviews

♥ 11 Customer Favorites



**Vehicle serviced**

- Inspection performed
- Tire checked
- Maintenance inspection completed
- Tires rotated
- Oil and filter changed






01/04/2021 106,647

Van Bortel Subaru Of  
Rochester  
Rochester, NY  
888-309-5502  
vanbortelsubarurocheste  
rsoa.dealer.subaru.com/



**Vehicle serviced**

- Inspection performed
- Tire checked
- Maintenance inspection completed
- Recommended maintenance performed

		<p>★ <b>4.7 / 5.0</b> 105 Verified Reviews ♥ <b>11</b> Customer Favorites</p>	<ul style="list-style-type: none"> <li>- Tire(s) replaced</li> <li>- Lower ball joint(s) replaced</li> <li>- Alignment performed</li> <li>- Valve cover gasket(s) replaced</li> </ul>
01/05/2021		<p>New York Inspection Station</p>	<p><b>Passed safety inspection</b> - Passed emissions inspection</p>
07/08/2021	110,148	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ <b>4.8 / 5.0</b> 146 Verified Reviews ♥ <b>11</b> Customer Favorites</p>	<p> <b>Vehicle serviced</b> - Tires rotated - Oil and filter changed - Tire(s) replaced</p>
10/23/2021	113,324	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ <b>4.8 / 5.0</b> 146 Verified Reviews ♥ <b>11</b> Customer Favorites</p>	<p> <b>Vehicle serviced</b> - Oil and filter changed</p>
11/03/2021		<p>New York Motor Vehicle Dept. Rochester, NY</p>	<p><b>Registration issued or renewed</b> - Titled or registered as personal vehicle - Passed safety inspection</p>
01/18/2022	114,577	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ <b>4.8 / 5.0</b> 146 Verified Reviews ♥ <b>11</b> Customer Favorites</p>	<p> <b>Vehicle serviced</b> - Maintenance inspection completed - Tire(s) replaced</p>
01/18/2022	114,578	<p>New York Inspection Station</p>	<p><b>Passed safety inspection</b> - Passed emissions inspection</p>
03/21/2022	115,134	<p>Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/</p> <p>★ <b>4.7 / 5.0</b> 105 Verified Reviews ♥ <b>11</b> Customer Favorites</p>	<p> <b>Vehicle serviced</b> - Brakes checked</p>
05/27/2022	116,776	<p>Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502</p>	<p> <b>Vehicle serviced</b> - Maintenance inspection completed - Oil and filter changed</p>

vanbortelsubarurocheste  
rsoa.dealer.subaru.com/

★ 4.7 / 5.0

105 Verified Reviews

♥ 11 Customer Favorites

10/11/2022 120,777

Van Bortel Subaru Of  
Rochester  
Rochester, NY  
888-309-5502  
vanbortelsubarurocheste  
rsoa.dealer.subaru.com/

★ 4.7 / 5.0

105 Verified Reviews

♥ 11 Customer Favorites



### Vehicle serviced

- Maintenance inspection completed
- Exterior light bulb(s) replaced
- Ball joint(s) replaced
- Oil and filter changed
- Cabin air filter replaced/cleaned
- Tail light assembly replaced
- Brake fluid flushed/changed
- Differential fluid flushed/changed
- Tire(s) replaced
- Light bulb(s) replaced
- Spark plug(s) replaced

11/06/2022

Damage Report





### Accident reported: minor to moderate damage

- It hit a deer
- Damage to front
- Damage to right front



**CARFAX HAS THE MOST  
ACCIDENT & DAMAGE  
INFORMATION**



12/23/2022 121,472

Bob Johnson Toyota  
Rochester, NY  
585-475-1700  
<https://dorscheltoyota.com/>



### Vehicle serviced

★ 4.7 / 5.0  
344 Verified Reviews  
♥ 10 Customer Favorites

01/19/2023 121,862 Van Bortel Subaru Of  
Rochester  
Rochester, NY  
888-309-5502  
vanbortelsubarurocheste  
rsoa.dealer.subaru.com/



**Vehicle serviced**  
- Tire(s) replaced  
- Battery replaced

★ 4.7 / 5.0  
105 Verified Reviews  
♥ 11 Customer Favorites

01/19/2023 121,863 New York  
Inspection Station

**Passed safety inspection**  
- Passed emissions inspection

08/15/2023 126,350 Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**  
- Maintenance inspection completed  
- Tires rotated  
- Tire(s) replaced  
- Oil and filter changed

★ 4.8 / 5.0  
146 Verified Reviews  
♥ 11 Customer Favorites



This vehicle's oil change history, as reported to CARFAX, follows the manufacturer's recommendation. Track your service history for free at [carfax.com/service](https://www.carfax.com/service).

Have Questions? Consumers, please visit our Help Center at [www.carfax.com](https://www.carfax.com). Dealers or Subscribers, please visit our Help Center at [www.carfaxonline.com](https://www.carfaxonline.com).



## Glossary

### Accident Indicator

CARFAX receives information about accidents in all 50 states, the District of Columbia and Canada.

Not every accident is reported to CARFAX. As details about the accident become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- According to the National Safety Council, Injury Facts, 2021 edition, 5% of the 276 million registered vehicles in the U.S. were involved in an accident in 2019. Over 77% of these were considered minor or moderate.
- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 9/10/23 at 10:00:56 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

### CARFAX Well Maintained - Regular Oil Changes

CARFAX identifies a "Well Maintained - Regular Oil Change" vehicle as having a regular oil change history when all its recommended oil changes, based on the vehicle's maintenance schedule, have been reported to CARFAX. CARFAX

uses the manufacturer's schedule and assumes normal driving conditions. When an oil change schedule is not available, CARFAX may analyze reported service events to determine what is typical for the same make and model vehicle. Dealers and service shops may publish different recommended service schedules.

### Damage Severity

Damage events result in one of the following severity levels:

- **Minor:** Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- **Moderate:** Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- **Severe:** Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

### First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

### Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

### Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



[facebook.com/CARFAX](https://www.facebook.com/CARFAX)



[@CARFAXinc](https://twitter.com/CARFAXinc)



[About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2023 CARFAX, Inc., part of S&P Global. All rights reserved.  
9/10/23 10:00:56 AM (CDT)

**I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2012 SUBARU OUTBACK vehicle (VIN: 4S4BRBGC3C3232634), which is based on information supplied to CARFAX and available as of 9/10/23 at 11:00 AM (EDT).**

\_\_\_\_\_  
**Customer Signature**

\_\_\_\_\_  
**Date**

\_\_\_\_\_  
**Dealer Signature**

\_\_\_\_\_  
**Date**