


Display CARFAX in online listings:




This report provided free of charge by:

Van Bortel Ford
 71 Marsh Rd
 East Rochester, NY 14445
 585-460-1438

2022 TOP RATED DEALER

★ **4.8 / 5.0**
 1,205 Verified Reviews

♥ **8,751**
 Customer Favorites






Vehicle History Report™


US \$44.99




<p>2011 SUBARU FORESTER 2.5X VIN: JF2SHABC0BH744444 4 DOOR WAGON/SPORT UTILITY 2.5L H4 F SOHC 16V GASOLINE ALL WHEEL DRIVE</p> <p>This CARFAX Report Provided by: Van Bortel Ford ★ 4.8 / 5.0 1,205 Verified Reviews ♥ 8,751 Customer Favorites</p>	<ul style="list-style-type: none"> <li style="margin-bottom: 10px;"> No accidents or damage reported to CARFAX <li style="margin-bottom: 10px;"> 34 Service history records <li style="margin-bottom: 10px;"> 2 Previous owners <li style="margin-bottom: 10px;"> Personal vehicle <li style="margin-bottom: 10px;"> Last owned in New York <li style="margin-bottom: 10px;"> 164,106 Last reported odometer reading
---	--

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 5/19/23 at 6:05:23 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

 Ownership History <small>The number of owners is estimated</small>	Owner 1	Owner 2
Year purchased	2011	2014
Type of owner	Personal	Personal
Estimated length of ownership	2 yrs. 6 mo.	9 yrs. 2 mo.
Owned in the following states/provinces	New York	New York
Estimated miles driven per year	8,879/yr	15,767/yr
Last reported odometer reading	23,180	164,106

 Title History CARFAX guarantees the information in this section	Owner 1	Owner 2
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. View Terms View Certificate		

 Additional History Not all accidents / issues are reported to CARFAX	Owner 1	Owner 2
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall Check with an authorized Subaru dealer for any open recalls.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired

 Detailed History			
 Owner 1 Purchased: 2011		Low mileage! This owner drove less than the industry average of 15,000 miles per year.	Personal Vehicle 8,879 mi/yr
Date	Mileage	Source	Comments
04/21/2011		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com	Vehicle offered for sale

★ 4.8 / 5.0
137 Verified Reviews
♥ 11 Customer Favorites

04/26/2011 7

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Pre-delivery inspection completed
- Safety inspection performed

★ 4.8 / 5.0
137 Verified Reviews
♥ 11 Customer Favorites

04/27/2011

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

Vehicle sold

★ 4.8 / 5.0
137 Verified Reviews
♥ 11 Customer Favorites

04/27/2011

New York
Inspection Station

Emissions inspection performed

- Passed safety inspection

05/24/2011

New York
Motor Vehicle Dept.
Naples, NY

Title issued or updated

- Registration issued or renewed
- First owner reported
- Titled or registered as personal vehicle
- Passed safety inspection

06/17/2011 1,577

Inspection Co.
New York

Inspection performed

06/22/2011

Farnsworth Chevrolet
Canandaigua, NY
585-394-2360
farnsworthgroup.com



Vehicle serviced

- Maintenance inspection completed

★ 4.8 / 5.0
58 Verified Reviews

10/28/2011 4,599

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

★ 4.8 / 5.0
137 Verified Reviews
♥ 11 Customer Favorites

03/13/2012

New York
Motor Vehicle Dept.
Naples, NY






Registration issued or renewed

- Titled or registered as personal vehicle
- Passed safety inspection

04/10/2012 7,993




New York

Passed safety inspection






		Inspection Station	- Emissions inspection performed
04/08/2013	17,199	New York Inspection Station	Passed safety inspection - Passed emissions inspection
07/03/2013	20,432	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 137 Verified Reviews ♥ 11 Customer Favorites	 Vehicle serviced - Sunvisor(s) replaced/repared
12/03/2013	23,136	Subaru Certified Dealer Victor, NY 	Offered for sale as a Subaru Certified Pre-owned Vehicle
12/03/2013		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 137 Verified Reviews ♥ 11 Customer Favorites	Vehicle offered for sale
12/03/2013		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 137 Verified Reviews ♥ 11 Customer Favorites 	 Vehicle serviced - Air filter replaced - Rear brake pads replaced - Rear brake rotor(s) replaced - Remote(s) programmed - Oil and filter changed <div data-bbox="868 1449 1502 1564" style="border: 1px solid blue; padding: 5px; margin-top: 10px;">Looks like this dealer serviced the car in order to prepare it for sale. That's a good thing!</div>
01/29/2014	23,151	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 137 Verified Reviews ♥ 11 Customer Favorites	 Vehicle serviced - Safety inspection performed
02/01/2014	23,180	New York Inspection Station	Passed safety inspection - Failed emissions inspection

02/03/2014	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 137 Verified Reviews ❤️ 11 Customer Favorites	Vehicle sold
02/03/2014	New York Motor Vehicle Dept. Rochester, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection

 Owner 2 Purchased: 2014	Personal Vehicle 15,767 mi/yr
---	----------------------------------

Date	Mileage	Source	Comments
02/26/2014		New York Motor Vehicle Dept. Rochester, NY	Title issued or updated - New owner reported
08/14/2014	31,616	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 137 Verified Reviews ❤️ 11 Customer Favorites	 Vehicle serviced - Oil pan drain plug replaced - Oil and filter changed
02/11/2015	39,828	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 137 Verified Reviews ❤️ 11 Customer Favorites	 Vehicle serviced - Safety inspection performed - Oil and filter changed - Emissions inspection performed
02/11/2015		New York Inspection Station	Passed safety inspection - Passed emissions inspection
02/27/2015		New York Motor Vehicle Dept. Rochester, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
08/26/2015	49,527	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 137 Verified Reviews ❤️ 11 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Engine checked - Engine/powertrain computer/module checked - Oil and filter changed - Cabin air filter replaced/cleaned - Air filter replaced

- Two tires balanced
- Tires rotated

01/22/2016		<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 137 Verified Reviews ❤️ 11 Customer Favorites</p>	 <p>Vehicle serviced</p> <ul style="list-style-type: none"> - Brakes serviced - Oil and filter changed - Safety inspection performed
01/22/2016	57,570	<p>New York Inspection Station</p>	<p>Passed safety inspection</p> <ul style="list-style-type: none"> - Passed emissions inspection
10/03/2016	71,694	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 137 Verified Reviews ❤️ 11 Customer Favorites</p>	 <p>Vehicle serviced</p> <ul style="list-style-type: none"> - Light bulb(s) replaced - Oil and filter changed - Tire condition and pressure checked
12/07/2016		<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 137 Verified Reviews ❤️ 11 Customer Favorites</p>	 <p>Vehicle serviced</p> <ul style="list-style-type: none"> - Four wheel alignment performed - Four tires mounted
01/23/2017	76,745	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 137 Verified Reviews ❤️ 11 Customer Favorites</p>	 <p>Vehicle serviced</p> <ul style="list-style-type: none"> - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked - Safety inspection performed
01/23/2017		<p>New York Inspection Station</p>	<p>Passed safety inspection</p> <ul style="list-style-type: none"> - Passed emissions inspection
03/10/2017		<p>New York Motor Vehicle Dept. Rochester, NY</p>	<p>Registration issued or renewed</p> <ul style="list-style-type: none"> - Titled or registered as personal vehicle - Passed safety inspection
10/02/2017	91,647	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 137 Verified Reviews ❤️ 11 Customer Favorites</p>	 <p>Vehicle serviced</p> <ul style="list-style-type: none"> - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked - Cabin air filter replaced/cleaned - Four tires balanced

- Tires rotated

01/29/2018 97,870

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

★ 4.8 / 5.0

137 Verified Reviews

♥ 11 Customer Favorites



Vehicle serviced

- Oil and filter changed
- Safety inspection performed
- Emissions inspection performed

01/29/2018

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

08/03/2018 107,160

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

★ 4.8 / 5.0

137 Verified Reviews

♥ 11 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Oil and filter changed

11/02/2018 111,108

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

★ 4.8 / 5.0

137 Verified Reviews

♥ 11 Customer Favorites



Vehicle serviced

- Light bulb(s) replaced

11/16/2018 111,610

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

★ 4.8 / 5.0

137 Verified Reviews

♥ 11 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Cabin air filter replaced/cleaned
- Air filter checked
- Oil and filter changed
- Tire condition and pressure checked
- Wipers/washers checked
- Battery replaced
- Air filter replaced

01/26/2019 114,180

Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

★ 4.7 / 5.0

94 Verified Reviews

♥ 8 Customer Favorites



Vehicle serviced

- Inspection performed
- Tire checked
- Maintenance inspection completed
- Emissions or safety inspection performed

01/26/2019

New York
Inspection Station






Passed safety inspection

- Passed emissions inspection

02/05/2019

New York

Registration issued or renewed

		Motor Vehicle Dept. Rochester, NY		- Titled or registered as personal vehicle - Passed safety inspection
02/08/2019	114,835	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.7 / 5.0 94 Verified Reviews ❤️ 8 Customer Favorites		Vehicle serviced - Inspection performed - Tire checked - Maintenance inspection completed
11/01/2019	126,376	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.7 / 5.0 94 Verified Reviews ❤️ 8 Customer Favorites		Vehicle serviced - Inspection performed - Tire checked - Maintenance inspection completed - Air filter replaced - Vehicle washed/detailed - Oil and filter changed
01/24/2020	130,321	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.7 / 5.0 94 Verified Reviews ❤️ 8 Customer Favorites		Vehicle serviced - Inspection performed - Tire checked - Maintenance inspection completed - Oil and filter changed - Tires rotated - Emissions or safety inspection performed
01/24/2020		New York Inspection Station		Passed safety inspection - Passed emissions inspection
07/24/2020	137,123	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/ ★ 4.7 / 5.0 94 Verified Reviews ❤️ 8 Customer Favorites		Vehicle serviced - Inspection performed - Tire checked - Maintenance inspection completed - Two tires balanced - Tires rotated - Oil and filter changed - Tire(s) replaced - Wiper(s) replaced - Tire pressure monitoring system reset
11/20/2020	140,307	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/		Vehicle serviced - Maintenance inspection completed

★ 4.7 / 5.0
94 Verified Reviews
♥ 8 Customer Favorites

01/15/2021 142,356 Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/
★ 4.7 / 5.0
94 Verified Reviews
♥ 8 Customer Favorites



Vehicle serviced
- Inspection performed
- Tire checked
- Air filter replaced
- Oil and filter changed
- Tire(s) replaced
- Front brake rotor(s) replaced
- Front brake pads replaced

01/15/2021 New York
Inspection Station

Passed safety inspection
- Passed emissions inspection

02/15/2021 143,411 Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/
★ 4.7 / 5.0
94 Verified Reviews
♥ 8 Customer Favorites



Vehicle serviced
- Inspection performed
- Tire checked
- Hood latch replaced
- Hood release cable replaced

02/17/2021 New York
Motor Vehicle Dept.
Rochester, NY

Registration issued or renewed
- Titled or registered as personal vehicle
- Passed safety inspection

05/28/2021 146,581 Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/
★ 4.7 / 5.0
94 Verified Reviews
♥ 8 Customer Favorites



Vehicle serviced
- Maintenance inspection completed
- Tire(s) replaced

09/03/2021 149,112 Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com
★ 4.8 / 5.0
137 Verified Reviews
♥ 11 Customer Favorites



Vehicle serviced
- Tires rotated
- Oil and filter changed
- Tire(s) replaced

11/19/2021 151,873 Van Bortel Subaru Of
Rochester
Rochester, NY



Vehicle serviced

888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

★ 4.7 / 5.0

94 Verified Reviews

♥ 8 Customer Favorites

01/14/2022 153,173

Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

★ 4.7 / 5.0

94 Verified Reviews

♥ 8 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Cabin air filter replaced/cleaned
- Tire(s) replaced

01/14/2022

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

02/14/2022 153,814

Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

★ 4.7 / 5.0

94 Verified Reviews

♥ 8 Customer Favorites



Vehicle serviced

- Tire(s) replaced

05/28/2022 156,487

Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

★ 4.7 / 5.0

94 Verified Reviews

♥ 8 Customer Favorites



Vehicle serviced

- Battery serviced
- Oil and filter changed

10/04/2022

Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

★ 4.7 / 5.0

94 Verified Reviews

♥ 8 Customer Favorites



Vehicle serviced

- Maintenance inspection completed

01/06/2023 164,106

Van Bortel Subaru Of
Rochester



Vehicle serviced

- Maintenance inspection completed

Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

★ 4.7 / 5.0

94 Verified Reviews

♥ 8 Customer Favorites

- Air filter replaced
- Wiper(s) replaced
- Oil and filter changed
- Emissions or safety inspection performed

01/06/2023

New York
Inspection Station

Passed safety inspection
- Passed emissions inspection

01/31/2023

New York
Motor Vehicle Dept.
Rochester, NY

Registration issued or renewed
- Titled or registered as personal vehicle
- Passed safety inspection

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

Failed Emissions Inspection

The emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Inspections

Many states or counties require annual or biennial emissions and/or safety inspections. Odometer readings are collected at the time of the inspection.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:  facebook.com/CARFAX

 [@CARFAXinc](https://twitter.com/CARFAXinc)

 [About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2023 CARFAX, Inc., part of S&P Global. All rights reserved.
5/19/23 6:05:23 AM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2011 SUBARU FORESTER vehicle (VIN: JF2SHABC0BH744444), which is based on information supplied to CARFAX and available as of 5/19/23 at 7:05 AM (EDT).

Customer Signature

Date

Dealer Signature

Date