


Display CARFAX in online listings:




This report provided free of charge by:

**Van Bortel Ford**  
 71 Marsh Rd  
 East Rochester, NY 14445  
 585-460-1438

**5X TOP-RATED DEALER**








★ **4.8 / 5.0**  
 1,619 Verified Reviews

♥ **10,633**  
 Customer Favorites




## Vehicle History Report™


US \$44.99

<p><b>2016 SUBARU FORESTER 2.5I</b>                  VIN: JF2SJABC6GH427053                  4 DOOR WAGON/SPORT UTILITY                  2.5L H4 F DOHC 16V GASOLINE                  ALL WHEEL DRIVE                  This CARFAX Report Provided by:  <b>Van Bortel Ford</b>                  ★ <b>4.8 / 5.0</b>                  1,619 Verified Reviews                  ♥ <b>10,633</b> Customer Favorites</p>	<ul style="list-style-type: none"> <li style="border-bottom: 1px solid #ccc; padding: 5px 0;"> No accidents or damage reported to CARFAX</li> <li style="border-bottom: 1px solid #ccc; padding: 5px 0;"> <b>19</b> Service history records</li> <li style="border-bottom: 1px solid #ccc; padding: 5px 0;"> CARFAX 1-Owner vehicle</li> <li style="border-bottom: 1px solid #ccc; padding: 5px 0;"> Personal vehicle</li> <li style="border-bottom: 1px solid #ccc; padding: 5px 0;"> Last owned in New York</li> <li style="padding: 5px 0;"> <b>111,520</b> Last reported odometer reading</li> </ul> 
--	--



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 11/20/24 at 11:56:20 AM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

 <b>Additional History</b> Not all accidents / issues are reported to CARFAX	<b>Owner 1</b>
<p><b>Total Loss</b>                      No total loss reported to CARFAX.</p>	<p> No Issues Reported</p>
<p><b>Structural Damage</b>                      No structural damage reported to CARFAX.</p>	<p> No Issues Reported</p>
<p><b>Airbag Deployment</b>                      No airbag deployment reported to CARFAX.</p>	<p> No Issues Reported</p>
<p><b>Odometer Check</b>                      No indication of an odometer rollback.</p>	<p> No Issues Indicated</p>

<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Manufacturer Recall</b> No open recalls reported to CARFAX.	<input checked="" type="checkbox"/> No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	<b>Warranty Expired</b>

<b>CARFAX Title History</b> CARFAX guarantees the information in this section	<b>Owner 1</b>
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
 <b>GUARANTEED</b> - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. <a href="#">View Terms</a>   <a href="#">View Certificate</a>	

<b>CARFAX Ownership History</b> The number of owners is estimated	<b>Owner 1</b>
Year purchased	2015
Type of owner	Personal
Estimated length of ownership	9 yrs. 1 mo.
Owned in the following states/provinces	New York
Estimated miles driven per year	12,391/yr
Last reported odometer reading	111,520

<b>CARFAX Detailed History</b>			
 <b>Owner 1</b> Purchased: 2015		<b>Low mileage!</b> This owner drove less than the industry average of 15,000 miles per year.	Personal Vehicle 12,391 mi/yr
<b>Date</b>	<b>Mileage</b>	<b>Source</b>	<b>Comments</b>
09/18/2015		Van Bortel Subaru Victor, NY 585-924-5230	<b>Vehicle offered for sale</b>

vanbortelsubaru.com

★ 4.8 / 5.0

180 Verified Reviews

♥ 8 Customer Favorites

09/28/2015 6

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

★ 4.8 / 5.0

180 Verified Reviews

♥ 8 Customer Favorites



**Vehicle serviced**

- Pre-delivery inspection completed
- Safety inspection performed
- Emissions or safety inspection performed

09/28/2015

New York  
Inspection Station

**Passed safety inspection**

- Emissions inspection performed

09/29/2015

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

★ 4.8 / 5.0

180 Verified Reviews

♥ 8 Customer Favorites

**Vehicle sold**

10/19/2015

New York  
Motor Vehicle Dept.  
Rochester, NY

**Title issued or updated**

- Registration issued or renewed
- First owner reported
- Titled or registered as personal vehicle
- Loan or lien reported
- Passed safety inspection

03/25/2016 5,964

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

★ 4.8 / 5.0

180 Verified Reviews

♥ 8 Customer Favorites



**Vehicle serviced**

- Maintenance inspection completed
- Tire condition and pressure checked
- Wipers/washers checked
- Remote start installed
- Oil and filter changed
- Four tires balanced
- Tires rotated
- Two tires balanced

09/26/2016 14,046

New York  
Inspection Station

**Passed safety inspection**

- Emissions inspection performed

12/27/2016 17,501

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

★ 4.8 / 5.0






180 Verified Reviews





♥ 8 Customer Favorites










**Vehicle serviced**

- Tire condition and pressure checked

07/07/2017	23,572	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 180 Verified Reviews ❤️ 8 Customer Favorites</p>	 <p><b>Vehicle serviced</b></p> <ul style="list-style-type: none"> <li>- Maintenance inspection completed</li> <li>- Tire condition and pressure checked</li> <li>- Wipers/washers checked</li> <li>- Oil and filter changed</li> <li>- Battery/charging system checked</li> <li>- Air filter replaced</li> <li>- Tire(s) balanced</li> <li>- Tires rotated</li> <li>- Tire pressure sensor reprogrammed</li> </ul>
08/29/2017		<p>New York Motor Vehicle Dept. Rochester, NY</p>	<p><b>Registration issued or renewed</b></p> <ul style="list-style-type: none"> <li>- Titled or registered as personal vehicle</li> <li>- Passed safety inspection</li> </ul>
09/20/2017	26,953	<p>New York Inspection Station</p>	<p><b>Passed safety inspection</b></p> <ul style="list-style-type: none"> <li>- Emissions inspection performed</li> </ul>
12/14/2017	29,968	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 180 Verified Reviews ❤️ 8 Customer Favorites</p>	 <p><b>Vehicle serviced</b></p> <ul style="list-style-type: none"> <li>- Maintenance inspection completed</li> <li>- Tires rotated</li> <li>- Tire pressure monitoring system reset</li> <li>- Oil and filter changed</li> </ul>
02/02/2018	31,129	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 180 Verified Reviews ❤️ 8 Customer Favorites</p>	 <p><b>Vehicle serviced</b></p>
07/06/2018	36,176	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 180 Verified Reviews ❤️ 8 Customer Favorites</p>	 <p><b>Vehicle serviced</b></p> <ul style="list-style-type: none"> <li>- Maintenance inspection completed</li> <li>- Tires rotated</li> <li>- Tire pressure monitoring system reset</li> <li>- Oil and filter changed</li> <li>- Brakes checked</li> </ul>
09/27/2018	38,593	<p>New York Inspection Station</p>	<p><b>Passed safety inspection</b></p> <ul style="list-style-type: none"> <li>- Passed emissions inspection</li> </ul>
12/18/2018	42,656	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 180 Verified Reviews ❤️ 8 Customer Favorites</p>	 <p><b>Vehicle serviced</b></p> <ul style="list-style-type: none"> <li>- Maintenance inspection completed</li> <li>- Oil and filter changed</li> </ul>

08/12/2019	49,313	<p>Van Bortel Subaru of Rochester Rochester, NY 888-309-5502 vanbortelsubaruofrochester.com/</p> <p>★ 4.8 / 5.0 172 Verified Reviews ❤️ 16 Customer Favorites</p>	 <p><b>Vehicle serviced</b></p> <ul style="list-style-type: none"> <li>- Oil and filter changed</li> <li>- Brakes checked</li> <li>- Front brakes serviced</li> <li>- Rear brake pads replaced</li> <li>- Rear brake rotor(s) replaced</li> <li>- Tire condition and pressure checked</li> </ul>
08/24/2019		<p>New York Motor Vehicle Dept. Rochester, NY</p>	<p><b>Registration issued or renewed</b></p> <ul style="list-style-type: none"> <li>- Titled or registered as personal vehicle</li> <li>- Passed safety inspection</li> </ul>
09/25/2019	50,622	<p>New York Inspection Station</p>	<p><b>Passed safety inspection</b></p> <ul style="list-style-type: none"> <li>- Passed emissions inspection</li> </ul>
03/05/2020	55,990	<p>Van Bortel Subaru of Rochester Rochester, NY 888-309-5502 vanbortelsubaruofrochester.com/</p> <p>★ 4.8 / 5.0 172 Verified Reviews ❤️ 16 Customer Favorites</p>	 <p><b>Vehicle serviced</b></p> <ul style="list-style-type: none"> <li>- Maintenance inspection completed</li> <li>- Oil and filter changed</li> <li>- Two tires balanced</li> <li>- Tires rotated</li> <li>- Tire pressure monitoring system reset</li> </ul>
09/18/2020	61,660	<p>Van Bortel Subaru of Rochester Rochester, NY 888-309-5502 vanbortelsubaruofrochester.com/</p> <p>★ 4.8 / 5.0 172 Verified Reviews ❤️ 16 Customer Favorites</p>	 <p><b>Vehicle serviced</b></p> <ul style="list-style-type: none"> <li>- Maintenance inspection completed</li> <li>- Recommended maintenance performed</li> <li>- Differential fluid flushed/changed</li> <li>- Two tires balanced</li> <li>- Tires rotated</li> <li>- Oil and filter changed</li> <li>- Rear wiper blade replaced</li> <li>- Spark plug(s) replaced</li> <li>- Tire pressure monitoring system reset</li> </ul>
09/18/2020	61,662	<p>New York Inspection Station</p>	<p><b>Passed safety inspection</b></p> <ul style="list-style-type: none"> <li>- Passed emissions inspection</li> </ul>
03/30/2021	67,763	<p>Van Bortel Subaru of Rochester Rochester, NY 888-309-5502 vanbortelsubaruofrochester.com/</p> <p>★ 4.8 / 5.0 172 Verified Reviews ❤️ 16 Customer Favorites</p>	 <p><b>Vehicle serviced</b></p> <ul style="list-style-type: none"> <li>- Inspection performed</li> <li>- Tire checked</li> <li>- Maintenance inspection completed</li> <li>- Tires rotated</li> <li>- Oil and filter changed</li> </ul>
09/09/2021		<p>New York</p>	<p><b>Registration issued or renewed</b></p>

		Motor Vehicle Dept. Rochester, NY		- Titled or registered as personal vehicle - Passed safety inspection
09/22/2021	74,343	Van Bortel Subaru of Rochester Rochester, NY 888-309-5502 vanbortelsubaruofroches ter.com/ ★ 4.8 / 5.0 172 Verified Reviews ❤️ 16 Customer Favorites		<b>Vehicle serviced</b> - Maintenance inspection completed - Tires rotated - Oil and filter changed - Front wiper blades/refills replaced - Front brake rotor(s) replaced - Front brake pads replaced - Brake rotor(s) replaced - Brakes checked
09/22/2021		New York Inspection Station		<b>Passed safety inspection</b> - Passed emissions inspection
04/05/2022	80,316	Van Bortel Subaru of Rochester Rochester, NY 888-309-5502 vanbortelsubaruofroches ter.com/ ★ 4.8 / 5.0 172 Verified Reviews ❤️ 16 Customer Favorites		<b>Vehicle serviced</b> - Maintenance inspection completed - Air filter replaced - Oil and filter changed
09/21/2022	86,516	Van Bortel Subaru of Rochester Rochester, NY 888-309-5502 vanbortelsubaruofroches ter.com/ ★ 4.8 / 5.0 172 Verified Reviews ❤️ 16 Customer Favorites		<b>Vehicle serviced</b> - Two tires balanced - Tires rotated - Oil and filter changed - Tire pressure monitoring system reset
09/21/2022	86,518	New York Inspection Station		<b>Passed safety inspection</b> - Passed emissions inspection
05/25/2023	93,236	Valvoline Instant Oil Change Greece, NY 585-621-1950 vioc.com ★ 4.7 / 5.0 228 Verified Reviews ❤️ 217 Customer Favorites		<b>Vehicle serviced</b> - Oil and filter changed - Light bulb(s) replaced - Air filter replaced
09/06/2023		New York Motor Vehicle Dept. Rochester, NY		<b>Registration issued or renewed</b> - Titled or registered as personal vehicle - Passed safety inspection
09/13/2023	97,962	New York		<b>Passed safety inspection</b>

		Inspection Station	- Passed emissions inspection
10/25/2023	99,589	Valvoline Instant Oil Change Greece, NY 585-621-1950 vioc.com ★ 4.7 / 5.0 228 Verified Reviews ❤️ 217 Customer Favorites	 <b>Vehicle serviced</b> - Battery replaced - Oil and filter changed
04/11/2024	104,739	Valvoline Instant Oil Change Greece, NY 585-621-1950 vioc.com ★ 4.7 / 5.0 228 Verified Reviews ❤️ 217 Customer Favorites	 <b>Vehicle serviced</b> - Oil and filter changed
08/08/2024	108,730	Valvoline Instant Oil Change Greece, NY 585-621-1950 vioc.com ★ 4.7 / 5.0 228 Verified Reviews ❤️ 217 Customer Favorites	 <b>Vehicle serviced</b> - Front wiper blades/refills replaced - Differential fluid flushed/changed - Rear differential fluid flushed/changed - Oil and filter changed - Cabin air filter replaced/cleaned
09/26/2024	111,520	New York Inspection Station	<b>Passed safety inspection</b> - Passed emissions inspection

Have Questions? Consumers, please visit our Help Center at [www.carfax.com](http://www.carfax.com). Dealers or Subscribers, please visit our Help Center at [www.carfaxonline.com](http://www.carfaxonline.com).



## Glossary

### First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

### Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

### Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:  [facebook.com/CARFAX](https://facebook.com/CARFAX)

 @CARFAXinc

 About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.  
11/20/24 11:56:20 AM (CST)

**I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2016 SUBARU FORESTER vehicle (VIN: JF2SJABC6GH427053), which is based on information supplied to CARFAX and available as of 11/20/24 at 12:56 PM (EST).**

---

**Customer Signature**

**Date**

---

**Dealer Signature**

**Date**