



CARFAX® Vehicle History Report™

An independent company established in 1986

US \$39.99

Vehicle Information:
2010 SUBARU OUTBACK 2.5I PREMIUM
 VIN:4S4BRBCC9A3312426
 4 DOOR WAGON/SPORT UTILITY
 2.5L H4 F SOHC 16V
 GASOLINE
 ALL WHEEL DRIVE
[Standard Equipment](#) | [Safety Options](#)


This CARFAX Report Provided by:
 Van Bortel Ford
 71 Marsh Rd
 East Rochester, NY 14445
 833-205-1341
 www.vanbortelford.com

4.7 ★★★★★
 22 Verified Reviews



	No accidents reported to CARFAX
	Damage reported
	CARFAX 1-Owner vehicle
	47 Service history records
	Personal vehicle
	160,251 Last reported odometer reading










This CARFAX Vehicle History Report is based only on [information](#) supplied to CARFAX and available as of 6/4/19 at 12:18:42 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

 Ownership History	Owner 1
The number of owners is estimated	
Year purchased	2009
Type of owner	Personal
Estimated length of ownership	9 yrs. 9 mo.
Owned in the following states/provinces	New York
Estimated miles driven per year	16,532/yr
Last reported odometer reading	160,251



 Title History	Owner 1
CARFAX guarantees the information in this section	
Salvage Junk Rebuilt Fire Flood Hail Lemon	Guaranteed No Problem
Not Actual Mileage Exceeds Mechanical Limits	Guaranteed No Problem
 <p>GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. Register View Terms View Certificate</p>	


 Additional History	Owner 1
Not all accidents / issues are reported to CARFAX	
Total Loss No total loss reported to CARFAX.	 No Issues Reported
Structural Damage No structural damage reported to CARFAX.	 No Issues Reported

Airbag Deployment No airbag deployment reported to CARFAX.	 No Issues Reported
Odometer Check No indication of an odometer rollback.	 No Issues Indicated
Accident / Damage Damage reported on 10/07/2013.	 Damage Reported
Manufacturer Recall Check with an authorized Subaru dealer for any open recalls.	 No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired



Detailed History








[Glossary](#)

 Owner 1	Date:	Mileage:	Source:	Comments:
Purchased: 2009 Type: Personal Where: New York Est. miles/year: 16,532/yr Est. length: 8/28/09 - owned: 5/30/19 (9 yrs. 9 mo.)	08/14/2009	8	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Pre-delivery inspection completed
	08/27/2009	15	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Safety inspection performed Emissions or safety inspection performed
	08/27/2009		New York Inspection Station	Emissions inspection performed Passed safety inspection View what was inspected
	08/28/2009		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Vehicle sold
	08/28/2009		New York Motor Vehicle Dept. Fairport, NY	Title issued or updated Registration issued or renewed First owner reported Titled or registered as personal vehicle Loan or lien reported Passed safety inspection
	10/16/2009		New York Motor Vehicle Dept. Fairport, NY	Title issued or updated Loan or lien reported
	11/03/2009	3,519	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Oil and filter changed

12/09/2009	5,295	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Vehicle serviced
02/16/2010	8,286	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	7,500 mile service performed Nitrogen fill tires
04/26/2010	11,644	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Oil and filter changed
06/28/2010	14,505	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Oil and filter changed
08/31/2010	16,731	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	15,000 mile service performed Safety inspection performed Emissions or safety inspection performed
08/31/2010		New York Inspection Station	Emissions inspection performed Passed safety inspection View what was inspected
11/19/2010	20,364	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Oil and filter changed
02/15/2011	23,963	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Recommended maintenance performed 22,500 mile service performed
05/25/2011	28,391	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Oil and filter changed
07/25/2011	30,504	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Recommended maintenance performed Safety inspection performed

07/25/2011		New York Inspection Station	Emissions inspection performed Passed safety inspection View what was inspected
07/26/2011		New York Motor Vehicle Dept. Fairport, NY	Registration issued or renewed Titled or registered as personal vehicle Passed safety inspection
11/16/2011	35,059	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Oil and filter changed
01/17/2012	37,527	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Recommended maintenance performed Headlight bulb(s) replaced
04/05/2012	40,969	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Oil and filter changed
07/11/2012	44,528	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Recommended maintenance performed 75,000 mile service performed Safety inspection performed Oil and filter changed Tire condition and pressure checked
07/12/2012		New York Inspection Station	Passed safety inspection Passed emissions inspection View what was inspected
08/22/2012	46,424	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Vehicle serviced
10/18/2012	49,762	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Oil and filter changed
11/20/2012	51,420	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Four wheel alignment performed Nitrogen fill tires Tire condition and pressure checked
01/09/2013	53,618	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Oil and filter changed


03/07/2013	56,062	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Oil and filter changed
06/05/2013	60,243	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Oil and filter changed
07/19/2013	61,720	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Recommended maintenance performed 60,000 mile service performed Safety inspection performed Brake rotor(s) replaced Oil and filter changed Tires rotated Emissions inspection performed
07/19/2013		New York Inspection Station	Passed safety inspection Passed emissions inspection View what was inspected
07/23/2013		New York Motor Vehicle Dept. Fairport, NY	Registration issued or renewed Titled or registered as personal vehicle Passed safety inspection
09/26/2013	65,448	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Oil and filter changed
10/07/2013		Damage Report	Damage reported Damage to left front Damage to front
			Not all damage is caused by an accident. Get the car inspected before you buy. Learn more
11/19/2013	67,613	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	67,500 mile service performed Tire condition and pressure checked Oil and filter changed
02/28/2014	72,091	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Oil and filter changed
06/11/2014	77,021	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Oil and filter changed

06/11/2014		New York Inspection Station	Passed safety inspection Emissions inspection performed View what was inspected
11/15/2014	85,008	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7  65 Verified Reviews	Vehicle serviced
01/26/2015	88,406	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7  65 Verified Reviews	Oil and filter changed
06/02/2015	93,924	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7  65 Verified Reviews	Maintenance inspection completed Oil and filter changed Cabin air filter replaced/cleaned Two tires balanced Tires rotated Safety inspection performed
06/02/2015		New York Inspection Station	Passed safety inspection Passed emissions inspection View what was inspected
07/23/2015		New York Motor Vehicle Dept. Fairport, NY	Registration issued or renewed Titled or registered as personal vehicle Passed safety inspection
10/07/2015	101,507	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7  65 Verified Reviews	Oil and filter changed Two tires balanced Tires rotated
03/23/2016	109,232	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7  65 Verified Reviews	Tire condition and pressure checked Battery/charging system checked Oil and filter changed Battery replaced Four tires balanced Tires rotated Two tires balanced
06/28/2016	114,060	New York Inspection Station	Passed safety inspection Passed emissions inspection View what was inspected
09/28/2016	119,768	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7  65 Verified Reviews	Vehicle serviced
11/02/2016	121,520	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7  65 Verified Reviews	Tire condition and pressure checked Four wheel alignment performed Oil and filter changed

03/16/2017	126,072	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Tire condition and pressure checked Oil and filter changed
06/19/2017	130,489	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Maintenance inspection completed Cabin air filter replaced/cleaned Oil and filter changed Safety inspection performed Rear brake pads replaced Rear brake rotor(s) replaced Four tires balanced Tires rotated Emissions inspection performed
06/19/2017		New York Inspection Station	Passed safety inspection Passed emissions inspection View what was inspected
07/20/2017		New York Motor Vehicle Dept. Fairport, NY	Registration issued or renewed Titled or registered as personal vehicle Passed safety inspection
10/16/2017	136,349	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Maintenance inspection completed Oil and filter changed
02/01/2018	141,625	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Maintenance inspection completed Cabin air filter replaced/cleaned Headlight bulb(s) replaced Tires rotated Tire pressure monitoring system reset Oil and filter changed
02/19/2018	142,505	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Vehicle serviced
06/14/2018	147,199	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Oil and filter changed Four tires balanced Tires rotated
06/14/2018		New York Inspection Station	Passed safety inspection Passed emissions inspection View what was inspected
09/24/2018		KROWN ROCHESTER East Rochester, NY 585-385-8866 https://krown.com/united-states/new-york/east-rochester/443/	Undercoating/rustproofing applied

11/17/2018	154,072	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Maintenance inspection completed Oil and filter changed Front brakes serviced
12/24/2018	155,406	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Maintenance inspection completed Headlight bulb(s) replaced Engine checked Fuel filler cap replaced
01/24/2019	156,620	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Vehicle serviced
02/18/2019	157,606	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Air filter checked Front brake rotor(s) replaced Front brake pads replaced Brake rotor(s) replaced Cabin air filter replaced/cleaned
03/06/2019	158,229	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Vehicle serviced
05/06/2019	160,251	Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubaruroche stersoa.dealer.subaru.com/	Oil and filter changed Four tires balanced Tires rotated
05/30/2019		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com 4.7 ★★★★★ 65 Verified Reviews	Vehicle offered for sale

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

[View Full Glossary](#)

Damage Indicator
 Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 6/4/19 at 12:18:42 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Inspections

Many states or counties require annual or biennial emissions and/or safety inspections. Odometer readings are collected at the time of the inspection.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:  [facebook.com/CARFAX](https://www.facebook.com/CARFAX)  [@CarfaxReports](https://twitter.com/CarfaxReports)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. CARFAX®

© 2019 CARFAX, Inc., a unit of IHS Markit. All rights reserved.

Covered by United States Patent Nos. 7,113,853; 7,778,841; 7,596,512, 8,600,823; 8,595,079; 8,606,648; 7,505,838.

6/4/19 12:18:42 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2010 SUBARU OUTBACK vehicle (VIN: 4S4BRBCC9A3312426), which is based on information supplied to CARFAX and available as of 6/4/19 at 1:18 PM (EDT).

Customer Signature

Date

Dealer Signature

Date