

This report is brought to you by:
VAN BORTEL FORD, INC.
71 MARSH ROAD
EAST ROCHESTER, NY 14445
585.586.4415
www.vanbortelford.net

Your AutoCheck Vehicle History Report

Report Run Date: November 26, 2018 9:36:12 AM EST

2016 Nissan Rogue S / SL / SV

VIN: 5N1AT2MM9GC802913

Class: CUV - Entry Level

Year: 2016

Engine: 2.5L I4 MPI

Make: Nissan

Country of Assembly: United States

Model: Rogue S / SL / SV

Vehicle Age: 2 year(s)

Style/Body: SUV 4D

Calculated Owners: 1



ONE OWNER

Calculated Owners: 1



Accident Check

Reported accidents: 1



State Title Brand and Other Problem Check

Your vehicle checks out:



Odometer Check


Your vehicle checks out:
Last Reported Odometer Reading:
4,526



Vehicle Use and Event Check

Specific vehicle use(s) or events reported

This vehicle's AutoCheck Score



The AutoCheck Score is a summary of your vehicle's history. It lets you compare similar vehicles with ease.

This vehicle is eligible for Buyback Protection



Due to the vehicle's history showing no reported major state title brands. [Click here](#) for terms and conditions and to register your vehicle.

Accident Check

Not all accidents / issues are reported to AutoCheck.



Information Reported: AutoCheck shows accidents reported to AutoCheck for this 2016 Nissan Rogue S / SL / SV (5N1AT2MM9GC802913). Below you will find the date and location reported for the accident. Not all accidents or damage events are reported to AutoCheck.



Accidents Reported on This Vehicle

Accident No.	Reported Date	Location
1	12/22/2017	MONROE COUNTY, NY

Reported accidents or damage events are a result of vehicle collisions or other non-collision incidents such as vandalism or theft. Not all accidents or damage events are reported to AutoCheck.

State Title Brand and Other Problem Check



Your Vehicle Checks Out: AutoCheck's database for this 2016 Nissan Rogue S / SL / SV (5N1AT2MM9GC802913) shows no negative titles or other problems. When reported to AutoCheck, these events can indicate serious past damage or other significant problems. Check the [Vehicle Use and Event Check](#) for reported accidents that can affect vehicle safety and value.

**0 Problem(s)
Reported:**

15 State Title and Other Problem areas checked:

	No abandoned record
	No damaged or major damage incident record
	No fire damaged record
	No grey market record
	No hail damage record
	No insurance loss or probable total loss record
	No junk or scrapped record
	No manufacturer buyback or lemon record
	No odometer problem record
	No rebuilt or rebuildable record

	No salvage or salvage auction record
	No water damaged record
	No NHTSA crash test record
	No frame or structural damage record
	No recycling facility record

Odometer Check



Your Vehicle Checks Out: AutoCheck examined the reported odometer readings [reported to AutoCheck](#) for this 2016 Nissan Rogue S / SL / SV (5N1AT2MM9GC802913) and no indication of an odometer rollback or tampering was found. AutoCheck uses business rules to determine if reported odometer readings are significantly less than previously reported values. Not all reported odometer readings are used. Title and auction events also report odometer tampering or breakage.

0 Problem(s) Reported:

	Mileage	Date Reported
--	---------	---------------

	17	04/26/2016
	4,526	12/02/2016




Vehicle Use and Event Check















Information Reported: AutoCheck shows additional vehicle uses or events [reported to AutoCheck](#) for this 2016 Nissan Rogue S / SL / SV (5N1AT2MM9GC802913). This includes reported vehicle uses such as rental or lease, and events such as whether the vehicle has been reported to have had a loan/lien or a duplicate title issued. Other events show if the vehicle has a reported accident and how many calculated accidents or if it has been reported stolen or repossessed. It is recommended to have pre-owned vehicles inspected by a third party prior to purchase.

0 Event(s) Reported:

6 Vehicle uses checked:

	No fleet, rental and/or lease use record
	No taxi use record
	No police use record

	No government use record
	No livery use record
	No driver education record
2 Event(s) Reported:	9 Vehicle events checked:
	1 Accident record(s) reported through accident data sources
	No corrected title record
	No duplicate title record
	No emission/safety inspection record
	Loan/Lien record(s)
	No fire damage incident record
	No repossessed record
	No theft record
	No storm area registration/title record

Continued on next page

Detailed Vehicle History

Below are the historical events for this vehicle listed in chronological order. Any discrepancies will be in bold text.

Report Run Date November 26, 2018 9:36:12 AM EST

Vehicle: 2016 Nissan Rogue S / SL / SV (5N1AT2MM9GC802913)



Event date	Location	Odometer reading	Data Source	Details
02/03/2016	NY		Independent Source	VEHICLE MANUFACTURED AND SHIPPED TO DEALER
04/05/2016	ROCHESTER, NY		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
04/26/2016	NY	17	Motor Vehicle Dept.	TITLE (Lien Reported)
11/04/2016	ROCHESTER, NY		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
12/02/2016	ROCHESTER, NY	4,526	Motor Vehicle Dept.	TITLE (Lien Reported)
12/16/2017	ROCHESTER, NY		Motor Vehicle Dept.	REGISTRATION EVENT/RENEWAL
12/22/2017	MONROE COUNTY, NY		State Agency	COLLISION WITH ANOTHER VEHICLE (Case #:37052391)

This Vehicle's Glossary

Below are the specific definitions for events that appear in this vehicle's report.

More information is available in the full [AutoCheck glossary](#).

Term	Section Location	Definition
Loan/Lien	Vehicle Use and Event Check	A loan/lien is the legal right to take and hold or sell the vehicle of a debtor as security or payment for a debt. Normally, a vehicle will have a lien due to a loan or unpaid repair bill against the vehicle. Check with the seller to ensure that the lien has been satisfied.
Accident or Vehicle Damage	Vehicle Use and Event Check	Reported accidents or damage events are a result of vehicle collisions or other non-collision incidents such as vandalism or theft. Not all accidents or damage events are reported to AutoCheck. Certain accident or damage events are reported by the source to have resulted in minor, moderate or severe damage to the vehicle, or the events are calculated by AutoCheck to have resulted in minor, moderate or severe damage based on the information reported. It is

recommended to have pre-owned vehicles inspected by a third party prior to purchase.

AutoCheck Terms and Conditions

This report, and any reliance upon it, is subject to [AutoCheck Terms and Conditions](#) . If you obtained the report from a dealer, the dealer has been provided with these Terms & Conditions and can share them with you. These AutoCheck Terms and Conditions are also available at any time at www.autocheck.com/terms or by writing to Experian: Experian Automotive C/O AutoCheck Customer Service 955 American Lane Schaumburg IL 60173

Buyback Protection Terms and Conditions

This vehicle (5N1AT2MM9GC802913) qualifies for [AutoCheck Buyback Protection](#) . If you obtained the report from a dealer, the dealer has been provided with the terms and can share them with you. These Buyback Protection Terms and Conditions are also available to you at any time at www.autocheck.com/bbptterms or by writing to Experian: Experian Automotive C/O AutoCheckCustomer Service 955 American Lane Schaumburg IL 60173

About AutoCheck

AutoCheck vehicle history reports by Experian Automotive is the leading vehicle history reporting service. With expert data handling, the Experian Automotive database houses over 4 billion records on a half a billion vehicles. Every AutoCheck vehicle history report will give you confidence when buying or selling your next used vehicle, with superior customer service every step of the way.

Patent Notice

Certain aspects of this vehicle history report may be covered by U.S. Patent 8,005,759.