














Display CARFAX in online listings:


	This report provided free of charge by: <b>Van Bortel Ford</b> 71 Marsh Rd East Rochester, NY 14445 585-460-1438	<b>5X TOP-RATED DEALER</b> <b>★ 4.8 / 5.0</b> 1,435 Verified Reviews	<b>♥ 9,866</b> Customer Favorites
--	--	--	--------------------------------------

	<b>Vehicle History Report™</b>	US \$44.99
<b>2011 SUBARU LEGACY 2.5I LIMITED</b> VIN: 4S3BMBK60B3223523 SEDAN 4 DR 2.5L H4 F SOHC 16V GASOLINE ALL WHEEL DRIVE  This CARFAX Report Provided by: <b>Van Bortel Ford</b> <b>★ 4.8 / 5.0</b> 1,435 Verified Reviews <b>♥ 9,866</b> Customer Favorites	<ul style="list-style-type: none"><li> No accidents or damage reported to CARFAX</li><li> <b>50</b> Service history records</li><li> CARFAX 1-Owner vehicle</li><li> Personal vehicle</li><li> Last owned in New York</li><li> <b>143,495</b> Last reported odometer reading</li></ul>	




This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/28/24 at 9:08:18 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

 <b>Additional History</b> Not all accidents / issues are reported to CARFAX	<b>Owner 1</b>
<b>Total Loss</b> No total loss reported to CARFAX.	 No Issues Reported
<b>Structural Damage</b> No structural damage reported to CARFAX.	 No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	 No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	 No Issues Indicated

<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
<b>Manufacturer Recall</b> Check with an authorized Subaru dealer for any open recalls.	<input checked="" type="checkbox"/> No Recalls Reported
<b>Basic Warranty</b> Original warranty estimated to have expired.	<b>Warranty Expired</b>

<b>CARFAX Title History</b> CARFAX guarantees the information in this section	<b>Owner 1</b>
<b>Damage Brands</b> Salvage   Junk   Rebuilt   Fire   Flood   Hail   Lemon	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
<b>Odometer Brands</b> Not Actual Mileage   Exceeds Mechanical Limits	<input checked="" type="checkbox"/> <b>Guaranteed</b> No Problem
 <b>GUARANTEED</b> - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. <a href="#">View Terms</a>   <a href="#">View Certificate</a>	

<b>CARFAX Ownership History</b> The number of owners is estimated	<b>Owner 1</b>
Year purchased	2010
Type of owner	Personal
Estimated length of ownership	13 yrs. 5 mo.
Owned in the following states/provinces	New York
Estimated miles driven per year	10,745/yr
Last reported odometer reading	143,495

<b>CARFAX Detailed History</b>				
 <b>Owner 1</b> Purchased: 2010		<b>Low mileage!</b> This owner drove less than the industry average of 15,000 miles per year.	Personal Vehicle 10,745 mi/yr	
<b>Date</b>	<b>Mileage</b>	<b>Source</b>	<b>Comments</b>	
10/09/2010	6	Van Bortel Subaru Victor, NY 585-924-5230	 <b>Vehicle serviced</b> - Pre-delivery inspection completed - Safety inspection performed	

vanbortelsubaru.com

★ 4.8 / 5.0

157 Verified Reviews

♥ 7 Customer Favorites

- Emissions or safety inspection performed

10/11/2010

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

★ 4.8 / 5.0

157 Verified Reviews

♥ 7 Customer Favorites

**Vehicle sold**

10/11/2010

New York  
Inspection Station

**Emissions inspection performed**

- Passed safety inspection

10/11/2010

New York  
Motor Vehicle Dept.  
Canandaigua, NY

**Registration issued or renewed**

- Titled or registered as personal vehicle  
- Passed safety inspection

11/18/2010

New York  
Motor Vehicle Dept.  
Canandaigua, NY

**Title issued or updated**

- First owner reported

02/23/2011 3,673

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

★ 4.8 / 5.0

157 Verified Reviews

♥ 7 Customer Favorites



**Vehicle serviced**

- Oil and filter changed

06/07/2011 7,954

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

★ 4.8 / 5.0

157 Verified Reviews

♥ 7 Customer Favorites



**Vehicle serviced**

- Oil and filter changed

06/25/2011 9,066

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

★ 4.8 / 5.0

157 Verified Reviews

♥ 7 Customer Favorites



**Vehicle serviced**

07/13/2011 9,199

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

★ 4.8 / 5.0  
157 Verified Reviews  
♥ 7 Customer Favorites

10/03/2011 12,050

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

- Oil and filter changed  
- Emissions or safety inspection performed

★ 4.8 / 5.0  
157 Verified Reviews  
♥ 7 Customer Favorites

10/03/2011

New York  
Inspection Station

**Passed safety inspection**

- Emissions inspection performed

02/29/2012 17,283

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

- 15,000 mile service performed

★ 4.8 / 5.0  
157 Verified Reviews  
♥ 7 Customer Favorites

04/21/2012 19,608

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

- Engine checked  
- Engine/powertrain computer/module checked

★ 4.8 / 5.0  
157 Verified Reviews  
♥ 7 Customer Favorites

06/16/2012 21,864

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

- Oil and filter changed

★ 4.8 / 5.0  
157 Verified Reviews  
♥ 7 Customer Favorites

10/01/2012 25,195

New York  
Inspection Station

**Passed safety inspection**

- Emissions inspection performed

10/09/2012

New York  
Motor Vehicle Dept.  
Canandaigua, NY

**Registration issued or renewed**

- Titled or registered as personal vehicle  
- Passed safety inspection

01/26/2013 30,045

Valvoline Instant Oil  
Change  
Canandaigua, NY  
585-394-6370  
vioc.com



**Vehicle serviced**

- Oil and filter changed  
- Air filter replaced

★ 4.7 / 5.0  
200 Verified Reviews  
♥ 182 Customer Favorites

03/01/2013 32,738

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

- Recommended maintenance performed
- 30,000 mile service performed
- Oil and filter changed
- Tires rotated
- Cabin air filter replaced/cleaned

★ 4.8 / 5.0  
157 Verified Reviews  
♥ 7 Customer Favorites

06/14/2013 38,446

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

- Oil and filter changed

★ 4.8 / 5.0  
157 Verified Reviews  
♥ 7 Customer Favorites

10/02/2013 43,201

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

- Oil and filter changed
- Safety inspection performed

★ 4.8 / 5.0  
157 Verified Reviews  
♥ 7 Customer Favorites

10/02/2013

New York  
Inspection Station

**Passed safety inspection**

- Passed emissions inspection

01/17/2014 47,651

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

- Oil and filter changed

★ 4.8 / 5.0  
157 Verified Reviews  
♥ 7 Customer Favorites

05/17/2014 51,491

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

- Recommended maintenance performed
- Oil and filter changed

★ 4.8 / 5.0  
157 Verified Reviews  
♥ 7 Customer Favorites

08/11/2014 56,392

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

★ 4.8 / 5.0  
157 Verified Reviews  
♥ 7 Customer Favorites

09/27/2014

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

- Safety inspection performed
- Oil and filter changed
- Emissions or safety inspection performed

★ 4.8 / 5.0  
157 Verified Reviews  
♥ 7 Customer Favorites

09/27/2014

New York  
Inspection Station

**Passed safety inspection**

- Passed emissions inspection

09/28/2014

New York  
Motor Vehicle Dept.  
Canandaigua, NY

**Registration issued or renewed**

- Titled or registered as personal vehicle
- Passed safety inspection

10/20/2014 57,756

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

★ 4.8 / 5.0  
157 Verified Reviews  
♥ 7 Customer Favorites

11/25/2014 59,724

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

★ 4.8 / 5.0  
157 Verified Reviews  
♥ 7 Customer Favorites

01/24/2015 62,790

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com



**Vehicle serviced**

- Oil and filter changed

★ 4.8 / 5.0  
157 Verified Reviews  
♥ 7 Customer Favorites

04/18/2015 66,691







Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com








**Vehicle serviced**

- Recommended maintenance performed
- 60,000 mile service performed
- Rear brake pads replaced
- Oil and filter changed
- Tires rotated
- Cabin air filter replaced/cleaned

★ 4.8 / 5.0  
157 Verified Reviews  
♥ 7 Customer Favorites

08/17/2015	71,290	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ <b>4.8 / 5.0</b> 157 Verified Reviews ♥ <b>7</b> Customer Favorites</p>	 <p><b>Vehicle serviced</b> - Oil and filter changed</p>
10/02/2015	73,259	<p>Monro Auto Service &amp; Tire Centers Canandaigua, NY</p> <p>★ <b>4.7 / 5.0</b> 16 Verified Reviews</p>	 <p><b>Vehicle serviced</b> - Emissions inspection performed</p>
10/02/2015		<p>New York Inspection Station</p>	<p><b>Passed safety inspection</b> - Passed emissions inspection</p>
02/03/2016	77,388	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ <b>4.8 / 5.0</b> 157 Verified Reviews ♥ <b>7</b> Customer Favorites</p>	 <p><b>Vehicle serviced</b> - Oil and filter changed - Air filter replaced - Air filter checked - Two tires balanced - Tires rotated</p>
04/22/2016	79,589	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ <b>4.8 / 5.0</b> 157 Verified Reviews ♥ <b>7</b> Customer Favorites</p>	 <p><b>Vehicle serviced</b> - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked</p>
10/08/2016	84,085	<p>Valvoline Instant Oil Change Canandaigua, NY 585-394-6370 vioc.com</p> <p>★ <b>4.7 / 5.0</b> 200 Verified Reviews ♥ <b>182</b> Customer Favorites</p>	 <p><b>Vehicle serviced</b> - Oil and filter changed</p>
10/09/2016		<p>New York Motor Vehicle Dept. Canandaigua, NY</p>	<p><b>Registration issued or renewed</b> - Titled or registered as personal vehicle - Passed safety inspection</p>
10/31/2016	85,006	<p>Monro Auto Service &amp; Tire Centers Canandaigua, NY</p> <p>★ <b>4.7 / 5.0</b> 16 Verified Reviews</p>	 <p><b>Vehicle serviced</b> - Wiper(s) replaced - Wipers/washers checked - Emissions inspection performed</p>

10/31/2016		New York Inspection Station		<b>Passed safety inspection</b> - Passed emissions inspection
01/16/2017	88,610	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ <b>4.8 / 5.0</b> 157 Verified Reviews ❤️ <b>7</b> Customer Favorites		<b>Vehicle serviced</b> - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked - Engine checked
05/11/2017	92,592	Valvoline Instant Oil Change Canandaigua, NY 585-394-6370 vioc.com ★ <b>4.7 / 5.0</b> 200 Verified Reviews ❤️ <b>182</b> Customer Favorites		<b>Vehicle serviced</b> - Oil and filter changed
07/06/2017	95,570	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ <b>4.8 / 5.0</b> 157 Verified Reviews ❤️ <b>7</b> Customer Favorites		<b>Vehicle serviced</b> - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked - Front brake rotor(s) replaced - Front brake pads replaced - Brake rotor(s) replaced
10/12/2017	98,558	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ <b>4.8 / 5.0</b> 157 Verified Reviews ❤️ <b>7</b> Customer Favorites		<b>Vehicle serviced</b> - Emissions or safety inspection performed
10/12/2017		New York Inspection Station		<b>Passed safety inspection</b> - Passed emissions inspection
09/28/2018		New York Motor Vehicle Dept. Canandaigua, NY		<b>Registration issued or renewed</b> - Titled or registered as personal vehicle - Passed safety inspection
11/05/2018	107,122	New York Inspection Station		<b>Passed safety inspection</b> - Passed emissions inspection
03/11/2019	108,768	Valvoline Instant Oil Change Canandaigua, NY 585-394-6370 vioc.com		<b>Vehicle serviced</b> - Oil and filter changed - Battery replaced



★ 4.7 / 5.0  
200 Verified Reviews  
♥ 182 Customer Favorites

07/09/2019 112,888

Walmart Auto Care  
Center  
Canandaigua, NY  
585-393-4920  
<https://www.walmart.com>



**Vehicle serviced**  
- Oil and filter changed

★ 4.7 / 5.0  
62 Verified Reviews

11/19/2019

Monro Auto Service &  
Tire Centers  
Canandaigua, NY  
585-394-7120  
monro.com



**Vehicle serviced**  
- Maintenance inspection completed  
- Recommended maintenance performed

★ 4.7 / 5.0  
16 Verified Reviews

11/22/2019 116,591

New York  
Inspection Station

**Passed safety inspection**  
- Passed emissions inspection

02/26/2020 120,312

Master Tech Automotive  
Canandaigua, NY  
585-394-7333  
mtacanandaigua.com



**Vehicle serviced**  
- Exhaust pipe replaced  
- Exhaust system checked  
- Exhaust secured  
- Oil and filter changed  
- Exhaust system replaced

★ 5.0 / 5.0  
62 Verified Reviews  
♥ 1 Customer Favorite

10/06/2020

New York  
Motor Vehicle Dept.  
Canandaigua, NY

**Registration issued or renewed**  
- Titled or registered as personal vehicle  
- Passed safety inspection

11/25/2020 123,519

Master Tech Automotive  
Canandaigua, NY  
585-394-7333  
mtacanandaigua.com



**Vehicle serviced**  
- Light bulb(s) replaced  
- Oil and filter changed  
- Emissions or safety inspection performed

★ 5.0 / 5.0  
62 Verified Reviews  
♥ 1 Customer Favorite

11/25/2020

New York  
Inspection Station

**Passed safety inspection**  
- Passed emissions inspection

12/04/2020 123,597

Master Tech Automotive  
Canandaigua, NY  
585-394-7333  
mtacanandaigua.com



**Vehicle serviced**  
- Serpentine belt replaced

★ 5.0 / 5.0

62 Verified Reviews

 1 Customer Favorite

02/05/2021 124,385

Valvoline Instant Oil  
Change  
Canandaigua, NY  
585-394-6370  
vioc.com

 4.7 / 5.0

200 Verified Reviews

 182 Customer Favorites



**Vehicle serviced**


- Air filter replaced
- Oil and filter changed

02/24/2021 124,836

Van Bortel Subaru  
Victor, NY  
585-924-5230  
vanbortelsubaru.com

 4.8 / 5.0

157 Verified Reviews

 7 Customer Favorites



**Vehicle serviced**


- Maintenance inspection completed

06/15/2021 125,866

Master Tech Automotive  
Canandaigua, NY  
585-394-7333  
mtacanandaigua.com

 5.0 / 5.0

62 Verified Reviews

 1 Customer Favorite



**Vehicle serviced**

- Brakes checked

07/09/2021

New York  
Motor Vehicle Dept.  
Canandaigua, NY

**Registration issued or renewed**

- Correction to record
- Titled or registered as personal vehicle
- Passed safety inspection

09/08/2021 127,284

Master Tech Automotive  
Canandaigua, NY  
585-394-7333  
mtacanandaigua.com

 5.0 / 5.0

62 Verified Reviews

 1 Customer Favorite



**Vehicle serviced**

- Rear brake rotor(s) replaced
- Front brake rotor(s) replaced
- Front brake pads replaced

11/29/2021 128,610

Master Tech Automotive  
Canandaigua, NY  
585-394-7333  
mtacanandaigua.com

 5.0 / 5.0

62 Verified Reviews

 1 Customer Favorite



**Vehicle serviced**







- Oil and filter changed
- Emissions or safety inspection performed

11/29/2021

New York  
Inspection Station

**Passed safety inspection**

- Passed emissions inspection

06/15/2022	131,308	Master Tech Automotive Canandaigua, NY 585-394-7333 mtacanandaigua.com ★ 5.0 / 5.0 62 Verified Reviews ❤️ 1 Customer Favorite		<b>Vehicle serviced</b> - Tires rotated - Oil and filter changed - Spark plug(s) replaced - Air filter replaced - Cabin air filter replaced/cleaned
10/14/2022		New York Motor Vehicle Dept. Canandaigua, NY		<b>Registration issued or renewed</b> - Titled or registered as personal vehicle - Passed safety inspection
10/27/2022	134,067	Master Tech Automotive Canandaigua, NY 585-394-7333 mtacanandaigua.com ★ 5.0 / 5.0 62 Verified Reviews ❤️ 1 Customer Favorite		<b>Vehicle serviced</b> - Oil and filter changed - Emissions or safety inspection performed
10/27/2022		New York Inspection Station		<b>Passed safety inspection</b> - Passed emissions inspection
06/13/2023	138,107	Master Tech Automotive Canandaigua, NY 585-394-7333 mtacanandaigua.com ★ 5.0 / 5.0 62 Verified Reviews ❤️ 1 Customer Favorite		<b>Vehicle serviced</b> - Rear brake pads replaced - Rear brake rotor(s) replaced - Exhaust system checked
07/11/2023	138,555	Master Tech Automotive Canandaigua, NY 585-394-7333 mtacanandaigua.com ★ 5.0 / 5.0 62 Verified Reviews ❤️ 1 Customer Favorite		<b>Vehicle serviced</b> - Transmission fluid changed - Transmission serviced
09/05/2023	139,700	Valvoline Instant Oil Change Canandaigua, NY 585-394-6370 vioc.com ★ 4.7 / 5.0 200 Verified Reviews ❤️ 182 Customer Favorites		<b>Vehicle serviced</b> - Oil and filter changed
10/02/2023	141,920	Master Tech Automotive Canandaigua, NY 585-394-7333		<b>Vehicle serviced</b> - Emissions or safety inspection performed

mtacanandaigua.com

★ 5.0 / 5.0

62 Verified Reviews

♥ 1 Customer Favorite

10/02/2023

New York  
Inspection Station

**Passed safety inspection**  
- Passed emissions inspection

02/02/2024 143,411

Master Tech Automotive  
Canandaigua, NY  
585-394-7333  
mtacanandaigua.com



**Vehicle serviced**  
- Exhaust pipe replaced

★ 5.0 / 5.0

62 Verified Reviews

♥ 1 Customer Favorite

02/14/2024 143,495

Master Tech Automotive  
Canandaigua, NY  
585-394-7333  
mtacanandaigua.com



**Vehicle serviced**  
- Idler pulley replaced  
- Serpentine belt replaced

★ 5.0 / 5.0

62 Verified Reviews

♥ 1 Customer Favorite

Have Questions? Consumers, please visit our Help Center at [www.carfax.com](http://www.carfax.com). Dealers or Subscribers, please visit our Help Center at [www.carfaxonline.com](http://www.carfaxonline.com).



## Glossary

### First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

### Inspections

Many states or counties require annual or biennial emissions and/or safety inspections. Odometer readings are collected at the time of the inspection.

### Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

### Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



[facebook.com/CARFAX](https://www.facebook.com/CARFAX)



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

**I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2011 SUBARU LEGACY vehicle (VIN: 4S3BMBK60B3223523), which is based on information supplied to CARFAX and available as of 3/28/24 at 10:08 AM (EDT).**

---

**Customer Signature**

**Date**

---

**Dealer Signature**

**Date**