

Display CARFAX in online listings:



This report provided free of charge by:

Van Bortel Ford

71 Marsh Rd
East Rochester, NY 14445
585-460-1438

5X TOP-RATED DEALER

★ **4.8 / 5.0**
1,438 Verified Reviews

♥ **9,894**

Customer Favorites



Vehicle History Report™

US \$44.99

2011 SUBARU OUTBACK 2.5I PREMIUM

VIN: 4S4BRBCC5B3388601

4 DOOR WAGON/SPORT
UTILITY

2.5L H4 F DOHC 16V
GASOLINE

ALL WHEEL DRIVE

This CARFAX Report Provided
by:

Van Bortel Ford

★ **4.8 / 5.0**

1,438 Verified Reviews

♥ **9,894** Customer Favorites



Accident reported



49 Service history records



2 Previous owners



Types of owners: Personal lease, Personal



Last owned in New York



137,038 Last reported odometer reading

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/3/24 at 3:20:39 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.




Accident / Damage History


Not all accidents / issues are reported to CARFAX

Event 1

12/18/2012


Accident reported with another motor vehicle

 Additional History Not all accidents / issues are reported to CARFAX	Owner 1	Owner 2
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage Accident reported: 12/18/2012.	Accident Reported	No New Issues Reported
Manufacturer Recall Check with an authorized Subaru dealer for any open recalls.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired	Warranty Expired

 Title History CARFAX guarantees the information in this section	Owner 1	Owner 2
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. [View Terms](#) | [View Certificate](#)

 Ownership History The number of owners is estimated	Owner 1	Owner 2
Year purchased	2011	2014
Type of owner	Personal lease	Personal
Estimated length of ownership	3 yrs. 1 mo.	9 yrs. 9 mo.
Owned in the following states/provinces	New York	New York
Estimated miles driven per year	9,109/yr	10,732/yr

Last reported odometer reading

29,262

137,038




Detailed History
**Owner 1**






Purchased: 2011



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Lease
Vehicle
9,109 mi/yr

Date	Mileage	Source	Comments
02/17/2011	7	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ❤️ 7 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed - Safety inspection performed
02/17/2011	18	New York Inspection Station	Emissions inspection performed - Passed safety inspection
02/21/2011		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ❤️ 7 Customer Favorites	Vehicle sold
02/21/2011		New York Motor Vehicle Dept. Rochester, NY	Registration issued or renewed - Titled or registered as personal lease vehicle - Passed safety inspection
03/22/2011		New York Motor Vehicle Dept. Fort Worth, TX	Title issued or updated - First owner reported - Titled or registered as personal lease vehicle
			<p>Two states? Vehicle leasing companies often title a car in one state but register it to be driven in another.</p>
06/06/2011		New York Motor Vehicle Dept. Rochester, NY	Registration issued or renewed - Titled or registered as personal lease vehicle - Passed safety inspection
03/04/2012	11,094	New York	Passed safety inspection


		Inspection Station		- Emissions inspection performed
07/19/2012	14,243	Valvoline Instant Oil Change Brighton, NY 585-244-2183 vioc.com ★ 4.8 / 5.0 198 Verified Reviews ♥ 194 Customer Favorites		Vehicle serviced - Oil and filter changed - Tires rotated
12/18/2012		Damage Report		Accident reported with another motor vehicle
03/30/2013	19,887	New York Inspection Station		Failed safety inspection - Passed emissions inspection
03/30/2013		Monro Auto Service & Tire Centers Rochester, NY ★ 4.6 / 5.0 54 Verified Reviews ♥ 1 Customer Favorite		Vehicle serviced - Oil and filter changed - Tires rotated - Air filter replaced - Air filter checked - Emissions inspection performed
05/04/2013	20,477	Monro Auto Service & Tire Centers Rochester, NY ★ 4.6 / 5.0 54 Verified Reviews ♥ 1 Customer Favorite		Vehicle serviced - Emissions inspection performed
05/04/2013		New York Inspection Station		Passed safety inspection - Passed emissions inspection
05/31/2013		New York Motor Vehicle Dept. Rochester, NY		Registration issued or renewed - Titled or registered as personal lease vehicle - Passed safety inspection
04/14/2014		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ♥ 7 Customer Favorites		Vehicle offered for sale
04/23/2014	28,877	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0		Vehicle serviced - Recommended maintenance performed - 30,000 mile service performed - Safety inspection performed - Oil and filter changed

158 Verified Reviews
♥ 7 Customer Favorites

- Wiper(s) replaced
- Emissions inspection performed



Looks like this dealer serviced the car in order to prepare it for sale. That's a good thing!

05/01/2014	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ♥ 7 Customer Favorites	Vehicle sold
05/01/2014	New York Inspection Station	Passed safety inspection - Emissions inspection performed
05/01/2014	New York Motor Vehicle Dept. Rochester, NY	Registration issued or renewed - Titled or registered as personal lease vehicle - Passed safety inspection
05/10/2014 29,262	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced





Owner 2
Purchased: 2014



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
10,732 mi/yr

Date	Mileage	Source	Comments
06/09/2014		New York Motor Vehicle Dept. Rochester, NY	Title issued or updated - New owner reported
07/18/2014 33,003		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Oil and filter changed
11/04/2014 37,344		Van Bortel Subaru Victor, NY	 Vehicle serviced - Oil and filter changed

585-924-5230
vanbortelsubaru.com
★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites

04/21/2015 41,699

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com
★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Oil and filter changed
- Safety inspection performed
- Cabin air filter replaced/cleaned
- Emissions inspection performed

04/21/2015

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

05/19/2015 42,793

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com
★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites



Vehicle serviced

- Key(s) (re) programmed

08/05/2015 46,702

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com
★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites



Vehicle serviced

- Oil and filter changed

11/12/2015 50,336

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com
★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites



Vehicle serviced

- Oil and filter changed
- Tire condition and pressure checked

02/01/2016

New York
Motor Vehicle Dept.
Rochester, NY

Registration issued or renewed

- Titled or registered as personal vehicle
- Passed safety inspection


04/19/2016 54,359

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com
★ 4.8 / 5.0
158 Verified Reviews



Vehicle serviced

- Maintenance inspection completed
- Oil and filter changed
- Tire condition and pressure checked
- Wipers/washers checked
- Safety inspection performed
- Front brake rotor(s) replaced

 7 Customer Favorites

- Front brake pads replaced
- Brake rotor(s) replaced
- Body lubricated
- Emissions inspection performed

04/19/2016

New York
Inspection Station

Passed safety inspection


- Passed emissions inspection

05/04/2016 54,878

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

158 Verified Reviews

 7 Customer Favorites



Vehicle serviced


- Maintenance inspection completed
- Oil and filter changed
- Tire condition and pressure checked
- Wipers/washers checked

08/15/2016 59,529

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

158 Verified Reviews

 7 Customer Favorites



Vehicle serviced


- Air filter replaced
- Cabin air filter replaced/cleaned

11/29/2016 62,781

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

158 Verified Reviews

 7 Customer Favorites



Vehicle serviced


- Maintenance inspection completed
- Oil and filter changed
- Tire condition and pressure checked
- Wipers/washers checked
- Battery replaced
- Body lubricated

03/21/2017 65,578

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

158 Verified Reviews

 7 Customer Favorites



Vehicle serviced

- Oil and filter changed
- Rear brake pads replaced
- Rear brake rotor(s) replaced
- Brake rotor(s) replaced
- Safety inspection performed
- Tire condition and pressure checked
- Body lubricated

03/21/2017

New York
Inspection Station

Passed safety inspection


- Passed emissions inspection

06/19/2017 68,609

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0







158 Verified Reviews

 7 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Oil and filter changed
- Tire condition and pressure checked
- Wipers/washers checked
- Body lubricated

09/22/2017	73,637	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 158 Verified Reviews ♥ 7 Customer Favorites</p>	 <p>Vehicle serviced</p> <ul style="list-style-type: none"> - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked - Body lubricated
01/12/2018		<p>New York Motor Vehicle Dept. Rochester, NY</p>	<p>Registration issued or renewed</p> <ul style="list-style-type: none"> - Titled or registered as personal vehicle - Passed safety inspection
03/21/2018	77,613	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 158 Verified Reviews ♥ 7 Customer Favorites</p>	 <p>Vehicle serviced</p> <ul style="list-style-type: none"> - Oil and filter changed - Tire condition and pressure checked - Body lubricated
03/21/2018		<p>New York Inspection Station</p>	<p>Passed safety inspection</p> <ul style="list-style-type: none"> - Passed emissions inspection
07/25/2018	82,365	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 158 Verified Reviews ♥ 7 Customer Favorites</p>	 <p>Vehicle serviced</p> <ul style="list-style-type: none"> - Oil and filter changed - Tire condition and pressure checked - Body lubricated
10/16/2018	85,689	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 158 Verified Reviews ♥ 7 Customer Favorites</p>	 <p>Vehicle serviced</p> <ul style="list-style-type: none"> - Oil and filter changed - Tire condition and pressure checked - Body lubricated
01/30/2019	88,538	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 158 Verified Reviews ♥ 7 Customer Favorites</p>	 <p>Vehicle serviced</p> <ul style="list-style-type: none"> - Maintenance inspection completed - Tire condition and pressure checked - Oil and filter changed - Wipers/washers checked - Headlight bulb(s) replaced
03/22/2019	89,906	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p>	 <p>Vehicle serviced</p> <ul style="list-style-type: none"> - Maintenance inspection completed - Battery/charging system checked - Air filter replaced

★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites

- Oil and filter changed
- Brake fluid flushed/changed
- Tire pressure sensor reprogrammed
- Emissions or safety inspection performed

03/22/2019

New York
Inspection Station

Passed safety inspection
- Passed emissions inspection

07/23/2019 94,085

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced
- Maintenance inspection completed
- Oil and filter changed
- License plate light bulb(s) replaced

★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites

10/04/2019 97,986

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced
- Maintenance inspection completed
- Tail light bulb(s) replaced
- Oil and filter changed
- Light bulb(s) replaced
- Brakes checked
- Rear brake pads replaced
- Rear brake rotor(s) replaced
- Rear brake rotor(s) resurfaced

★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites

11/11/2019

Van Bortel Subaru of
Rochester
Rochester, NY
888-309-5502
vanbortelsubaruofroches
ter.com/



Inspection performed
- Tire checked

★ 4.8 / 5.0
141 Verified Reviews
♥ 15 Customer Favorites

12/06/2019 100,486

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced
- Maintenance inspection completed

★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites

12/31/2019

New York
Motor Vehicle Dept.
Rochester, NY

Registration issued or renewed
- Titled or registered as personal vehicle
- Passed safety inspection

02/19/2020 102,904

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced
- Wiper(s) replaced
- Tire condition and pressure checked
- Oil and filter changed

★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites

05/27/2020 104,334 Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced
- Antifreeze/coolant checked
- Oil and filter changed

★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites

05/27/2020 104,335 New York
Inspection Station

Passed safety inspection
- Passed emissions inspection

07/16/2020 105,126 Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced
- Timing belt replaced

★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites

11/13/2020 108,277 Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced
- Oil and filter changed

★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites

01/05/2021 109,348 Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced
- Tire condition and pressure checked
- Headlight bulb(s) replaced

★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites

03/30/2021 111,107 Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced
- Oil and filter changed
- Tire condition and pressure checked

★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites

05/13/2021 113,157 Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502



Vehicle serviced
- Maintenance inspection completed

vanbortelsubarurocheste
rsoa.dealer.subaru.com/

★ 4.8 / 5.0

141 Verified Reviews

♥ 15 Customer Favorites

05/14/2021

New York
Inspection Station

Passed safety inspection
- Passed emissions inspection

06/03/2021 113,891

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites

08/24/2021 114,215

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Oil and filter changed
- Tires rotated
- Front brakes replaced
- Front brake rotor(s) replaced
- Front brake pads replaced

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites

12/07/2021 116,671

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Maintenance inspection completed
- Oil and filter changed

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites

01/19/2022

New York
Motor Vehicle Dept.
Rochester, NY

Registration issued or renewed

- Titled or registered as personal vehicle
- Passed safety inspection

02/10/2022 118,499

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Maintenance inspection completed
- Oil and filter changed
- Light bulb(s) replaced
- Front wheel bearing(s)/hub(s) replaced

★ 4.8 / 5.0

158 Verified Reviews

♥ 7 Customer Favorites

05/10/2022 120,695

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com





















Vehicle serviced


- Tires rotated
- Oil and filter changed
- Rear wheel bearing(s)/hub(s) replaced
- Emissions or safety inspection performed

★ 4.8 / 5.0

158 Verified Reviews

 7 Customer Favorites


05/10/2022	120,697	New York Inspection Station		Passed safety inspection - Passed emissions inspection
06/11/2022	121,674	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 158 Verified Reviews  7 Customer Favorites		Vehicle serviced
07/13/2022	122,481	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 158 Verified Reviews  7 Customer Favorites		Vehicle serviced - Heat shield secured
09/20/2022	124,225	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 158 Verified Reviews  7 Customer Favorites		Vehicle serviced - Oil and filter changed
12/10/2022	126,151	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 158 Verified Reviews  7 Customer Favorites		Vehicle serviced - Tire condition and pressure checked
01/10/2023	126,760	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 158 Verified Reviews  7 Customer Favorites		Vehicle serviced - Oil and filter changed
03/29/2023	128,734	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com  4.8 / 5.0 158 Verified Reviews		Vehicle serviced

 7 Customer Favorites

05/23/2023 130,081 Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

158 Verified Reviews

 7 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Oil and filter changed

05/23/2023 New York
Inspection Station


Passed safety inspection

- Passed emissions inspection

11/06/2023 133,447 Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

158 Verified Reviews

 7 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Tires rotated
- Battery replaced
- Oil and filter changed

12/15/2023 New York
Motor Vehicle Dept.
Rochester, NY


Registration issued or renewed

- Titled or registered as personal vehicle
- Passed safety inspection

03/25/2024 137,038 Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

158 Verified Reviews

 7 Customer Favorites



Vehicle serviced

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

Accident Indicator

CARFAX receives information about accidents in all 50 states, the District of Columbia and Canada.

Not every accident is reported to CARFAX. As details about the accident become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- According to the National Safety Council, Injury Facts, 2021 edition, 5% of the 276 million registered vehicles in the U.S. were involved in an accident in 2019. Over 77% of these were considered minor or moderate.
- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/3/24 at 3:20:39 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Inspections

Many states or counties require annual or biennial emissions and/or safety inspections. Odometer readings are collected at the time of the inspection.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



facebook.com/CARFAX



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.
4/3/24 3:20:39 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2011 SUBARU OUTBACK vehicle (VIN: 4S4BRBCC5B3388601), which is based on information supplied to CARFAX and available as of 4/3/24 at 4:20 PM (EDT).

Customer Signature

Date

Dealer Signature

Date