





Display CARFAX in online listings:



	This report provided free of charge by: Van Bortel Ford 71 Marsh Rd East Rochester, NY 14445 585-460-1438	5X TOP-RATED DEALER ★ 4.8 / 5.0 1,427 Verified Reviews	♥ 9,813 Customer Favorites
--	--	--	--------------------------------------


	Vehicle History Report™	US \$44.99
2012 SUBARU OUTBACK 2.5I LIMITED VIN: 4S4BRBLC5C3202203 4 DOOR WAGON/SPORT UTILITY 2.5L H4 F DOHC 16V GASOLINE ALL WHEEL DRIVE This CARFAX Report Provided by: Van Bortel Ford ★ 4.8 / 5.0 1,427 Verified Reviews ♥ 9,813 Customer Favorites	Accident reported: minor damage  Regular oil changes 1 CARFAX 1-Owner vehicle Personal vehicle 141,843 Last reported odometer reading	


This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/15/24 at 9:37:34 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.




 Additional History Not all accidents / issues are reported to CARFAX	Owner 1
Total Loss No total loss reported to CARFAX.	✓ No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	✓ No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	✓ No Issues Reported
Odometer Check No indication of an odometer rollback.	✓ No Issues Indicated
Accident / Damage	Minor Damage


Accident reported: 10/27/2021.	
Manufacturer Recall Check with an authorized Subaru dealer for any open recalls.	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

 Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

 Ownership History The number of owners is estimated	Owner 1
Year purchased	2011
Type of owner	Personal
Estimated length of ownership	12 yrs. 3 mo.
Owned in the following states/provinces	New York
Estimated miles driven per year	11,474/yr
Last reported odometer reading	141,843





 Detailed History			
 Owner 1 Purchased: 2011 	<div style="border: 1px solid blue; padding: 5px;"> Low mileage! This owner drove less than the industry average of 15,000 miles per year. </div>		
Personal Vehicle 11,474 mi/yr			
Date	Mileage	Source	Comments
10/05/2011		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0	Vehicle offered for sale

157 Verified Reviews
 7 Customer Favorites

10/05/2011 5

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 **4.8 / 5.0**
157 Verified Reviews
 7 Customer Favorites





Vehicle serviced

- Pre-delivery inspection completed

10/27/2011 53

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 **4.8 / 5.0**
157 Verified Reviews
 7 Customer Favorites



Vehicle serviced

- Safety inspection performed
- Emissions or safety inspection performed

10/27/2011



New York
Inspection Station

Passed safety inspection

- Emissions inspection performed

10/28/2011

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 **4.8 / 5.0**
157 Verified Reviews
 7 Customer Favorites

Vehicle sold

11/25/2011



New York
Motor Vehicle Dept.
Pittsford, NY

Title issued or updated

- Registration issued or renewed
- First owner reported
- Titled or registered as personal vehicle
- Loan or lien reported
- Passed safety inspection

02/13/2012 2,766

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 **4.8 / 5.0**
157 Verified Reviews
 7 Customer Favorites




Vehicle serviced

- Oil and filter changed

05/02/2012 6,637


Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 **4.8 / 5.0**
157 Verified Reviews



Vehicle serviced

- Oil and filter changed


 7 Customer Favorites

06/16/2012 7,991

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

157 Verified Reviews

 7 Customer Favorites



Vehicle serviced

- Oil and filter changed
- Tire condition and pressure checked

10/05/2012 12,157

New York
Inspection Station

Passed safety inspection


- Emissions inspection performed

12/17/2012 14,433

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

157 Verified Reviews

 7 Customer Favorites



Vehicle serviced


- Oil and filter changed
- Computer reprogrammed

07/11/2013 21,198

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

157 Verified Reviews

 7 Customer Favorites



Vehicle serviced


- Oil and filter changed

09/24/2013 24,624

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

157 Verified Reviews

 7 Customer Favorites



Vehicle serviced

- Oil and filter changed
- Emissions or safety inspection performed

09/24/2013

New York
Inspection Station

Passed safety inspection

- Emissions inspection performed

09/30/2013

New York
Motor Vehicle Dept.
Pittsford, NY

Registration issued or renewed

- Titled or registered as personal vehicle
- Passed safety inspection

01/17/2014 27,514

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0







157 Verified Reviews


 7 Customer Favorites



















Vehicle serviced

- Oil and filter changed

02/13/2014	28,236	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites</p>		Vehicle serviced
03/03/2014	28,920	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites</p>		Vehicle serviced
05/15/2014	32,165	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites</p>		Vehicle serviced - Oil and filter changed
08/25/2014	35,589	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites</p>		Vehicle serviced - 30,000 mile service performed - Safety inspection performed - Four wheel alignment performed - Oil and filter changed - Tires rotated - Tire condition and pressure checked - Cabin air filter checked - Cabin air filter replaced/cleaned - Emissions inspection performed
08/25/2014		<p>New York Inspection Station</p>		Passed safety inspection - Passed emissions inspection
12/30/2014	39,472	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites</p>		Vehicle serviced - Oil and filter changed
04/15/2015	41,972	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 157 Verified Reviews</p>		Vehicle serviced - Oil and filter changed

 7 Customer Favorites

07/16/2015	44,433	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews  7 Customer Favorites	 Vehicle serviced - Safety inspection performed - Oil and filter changed - Emissions inspection performed
07/16/2015		New York Inspection Station	Passed safety inspection - Passed emissions inspection
09/30/2015		New York Motor Vehicle Dept. Pittsford, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
11/25/2015	49,665	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews  7 Customer Favorites	 Vehicle serviced - Recommended maintenance performed - Rear brake pads replaced - Rear brake rotor(s) replaced - Brake rotor(s) replaced - Oil and filter changed
03/08/2016	52,616	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews  7 Customer Favorites	 Vehicle serviced - Oil and filter changed - Rear wiper blade replaced
05/12/2016	54,577	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews  7 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked
06/09/2016	55,313	New York Inspection Station	Passed safety inspection - Passed emissions inspection
10/07/2016	59,696	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews  7 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked

02/23/2017	64,420	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Air filter replaced - Cabin air filter replaced/cleaned
04/26/2017	66,118	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Wiper(s) replaced
06/15/2017	67,374	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked - Safety inspection performed - Emissions inspection performed
06/15/2017		New York Inspection Station	Passed safety inspection - Passed emissions inspection
07/19/2017	68,345	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked
09/13/2017		New York Motor Vehicle Dept. Pittsford, NY	Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
09/19/2017	71,265	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Tire repaired - Oil and filter changed
01/03/2018	74,369	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com	 Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked

★ 4.8 / 5.0
157 Verified Reviews
♥ 7 Customer Favorites

- Battery replaced

05/24/2018 79,514

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Maintenance inspection completed
- Oil and filter changed

★ 4.8 / 5.0
157 Verified Reviews
♥ 7 Customer Favorites

06/13/2018 80,058

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Front brake rotor(s) replaced
- Front brake pads replaced
- Emissions inspection performed

★ 4.8 / 5.0
157 Verified Reviews
♥ 7 Customer Favorites

06/13/2018

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

08/30/2018 82,650

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Oil and filter changed
- Tire condition and pressure checked
- Brakes checked
- Rear wheel bearing(s)/hub(s) replaced

★ 4.8 / 5.0
157 Verified Reviews
♥ 7 Customer Favorites

09/27/2018 84,296

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Maintenance inspection completed
- Oil and filter changed
- Tire condition and pressure checked
- Wipers/washers checked

★ 4.8 / 5.0
157 Verified Reviews
♥ 7 Customer Favorites

11/20/2018 86,724

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Maintenance inspection completed
- Oil and filter changed

★ 4.8 / 5.0
157 Verified Reviews
♥ 7 Customer Favorites

12/19/2018 88,864

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

★ 4.8 / 5.0
157 Verified Reviews
♥ 7 Customer Favorites

02/13/2019 91,175

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

★ 4.8 / 5.0
157 Verified Reviews
♥ 7 Customer Favorites

02/25/2019 91,454

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Oil and filter changed

★ 4.8 / 5.0
157 Verified Reviews
♥ 7 Customer Favorites

03/21/2019 92,113

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

★ 4.8 / 5.0
157 Verified Reviews
♥ 7 Customer Favorites

06/13/2019 96,046

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Maintenance inspection completed
- Oil and filter changed
- Emissions or safety inspection performed

★ 4.8 / 5.0
157 Verified Reviews
♥ 7 Customer Favorites

06/13/2019

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

07/29/2019 99,072

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Maintenance inspection completed







★ 4.8 / 5.0
157 Verified Reviews
♥ 7 Customer Favorites






09/10/2019

New York
Motor Vehicle Dept.
Pittsford, NY


Registration issued or renewed

- Titled or registered as personal vehicle
- Passed safety inspection






10/09/2019	102,088	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites</p>	 <p>Vehicle serviced - Maintenance inspection completed - Oil and filter changed</p>
12/13/2019	106,989	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites</p>	 <p>Vehicle serviced - Maintenance inspection completed - Oil and filter changed</p>
06/17/2020	110,811	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites</p>	 <p>Vehicle serviced - Air filter replaced - Oil and filter changed - Front wiper blades/refills replaced - Emissions or safety inspection performed</p>
06/17/2020		<p>New York Inspection Station</p>	<p>Passed safety inspection - Passed emissions inspection</p>
09/09/2020	113,591	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites</p>	 <p>Vehicle serviced - Oil and filter changed</p>
02/01/2021	117,306	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites</p>	 <p>Vehicle serviced - Oil and filter changed</p>
05/17/2021	119,295	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites</p>	 <p>Vehicle serviced - Oil and filter changed - Tires rotated</p>

06/23/2021	120,888	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites</p>	 <p>Vehicle serviced</p> <ul style="list-style-type: none"> - Maintenance inspection completed - Rear brakes replaced - Differential fluid flushed/changed - Brake fluid flushed/changed - Air filter replaced - Oil and filter changed - Rear brake pads replaced - Rear brake rotor(s) replaced - Ball joint(s) replaced - Tires rotated - Antifreeze/coolant flushed/changed - Cabin air filter replaced/cleaned
06/23/2021		<p>New York Inspection Station</p>	<p>Passed safety inspection</p> <ul style="list-style-type: none"> - Passed emissions inspection
08/27/2021		<p>New York Motor Vehicle Dept. Pittsford, NY</p>	<p>Registration issued or renewed</p> <ul style="list-style-type: none"> - Titled or registered as personal vehicle - Passed safety inspection
08/31/2021	123,339	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites</p>	 <p>Vehicle serviced</p> <ul style="list-style-type: none"> - Oil and filter changed
09/17/2021		<p>Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 vanbortelsubarurocheste rsoa.dealer.subaru.com/</p> <p>★ 4.8 / 5.0 140 Verified Reviews ♥ 14 Customer Favorites</p>	 <p>Vehicle serviced</p>
10/01/2021	124,892	<p>Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com</p> <p>★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites</p>	 <p>Vehicle serviced</p> <ul style="list-style-type: none"> - Rear wheel bearing(s)/hub(s) replaced
10/27/2021		<p>Damage Report</p>	 <p>Accident reported: minor damage with another motor vehicle</p>

Damage Severity Scale



Minor damage is usually cosmetic, including dents or scratches to the vehicle body.

11/03/2021	126,726	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ❤️ 7 Customer Favorites	 Vehicle serviced - Tires rotated
01/08/2022	129,194	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ❤️ 7 Customer Favorites	 Vehicle serviced - Oil and filter changed - Battery replaced - Battery/charging system checked - Wiper(s) replaced
06/07/2022	133,421	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ❤️ 7 Customer Favorites	 Vehicle serviced - Maintenance inspection completed - Oil and filter changed
06/07/2022		New York Inspection Station	Passed safety inspection - Passed emissions inspection
10/29/2022	136,882	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ❤️ 7 Customer Favorites	 Vehicle serviced - Oil and filter changed - Drivability/performance checked
04/27/2023	138,069	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com	 Vehicle serviced - Maintenance inspection completed - Oil and filter changed

★ 4.8 / 5.0
157 Verified Reviews
♥ 7 Customer Favorites

06/22/2023 138,542 Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

★ 4.8 / 5.0
157 Verified Reviews
♥ 7 Customer Favorites

06/22/2023 New York
Inspection Station

Passed safety inspection
- Passed emissions inspection

08/16/2023 138,981 Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Maintenance inspection completed
- Rear brake pads replaced
- Front brake pads replaced

★ 4.8 / 5.0
157 Verified Reviews
♥ 7 Customer Favorites

09/12/2023 New York
Motor Vehicle Dept.
Pittsford, NY

Registration issued or renewed
- Titled or registered as personal vehicle
- Passed safety inspection

12/26/2023 140,071 Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Maintenance inspection completed
- Brake fluid flushed/changed
- Differential fluid flushed/changed
- Air filter replaced
- Two tires balanced
- Tires rotated
- Oil and filter changed
- Tire pressure monitoring system reset

★ 4.8 / 5.0
157 Verified Reviews
♥ 7 Customer Favorites

03/05/2024 141,843 Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

- Tire condition and pressure checked

★ 4.8 / 5.0
157 Verified Reviews
♥ 7 Customer Favorites



This vehicle's oil change history, as reported to CARFAX, follows the manufacturer's recommendation. Track your service history for free at [carfax.com/service](https://www.carfax.com/service).

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Accident Indicator

CARFAX receives information about accidents in all 50 states, the District of Columbia and Canada.

Not every accident is reported to CARFAX. As details about the accident become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- According to the National Safety Council, Injury Facts, 2021 edition, 5% of the 276 million registered vehicles in the U.S. were involved in an accident in 2019. Over 77% of these were considered minor or moderate.
- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/15/24 at 9:37:34 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Well Maintained - Regular Oil Changes

CARFAX identifies a "Well Maintained - Regular Oil Change" vehicle as having a regular oil change history when all its recommended oil changes, based on the vehicle's maintenance schedule, have been reported to CARFAX. CARFAX uses the manufacturer's schedule and assumes normal driving conditions. When an oil change schedule is not available, CARFAX may analyze reported service events to determine what is typical for the same make and model vehicle. Dealers and service shops may publish different recommended service schedules.

Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



facebook.com/CARFAX



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.
3/15/24 9:37:34 AM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2012 SUBARU OUTBACK vehicle (VIN: 4S4BRBLC5C3202203), which is based on information supplied to CARFAX and available as of 3/15/24 at 10:37 AM (EDT).

Customer Signature

Date

Dealer Signature

Date