

Display CARFAX in online listings:



This report provided free of charge by:

Van Bortel Ford

71 Marsh Rd
East Rochester, NY 14445
585-460-1438

5X TOP-RATED DEALER

★ **4.8 / 5.0**
1,438 Verified Reviews

♥ **9,894**

Customer Favorites



Vehicle History Report™

US \$44.99

**2014 SUBARU XV
CROSSTREK 2.0I
LIMITED**

VIN: JF2GPAGC1E8240099

4 DOOR WAGON/SPORT
UTILITY

2.0L H4 F DOHC 16V
GASOLINE

ALL WHEEL DRIVE

This CARFAX Report Provided
by:

Van Bortel Ford

★ **4.8 / 5.0**

1,438 Verified Reviews

♥ **9,894** Customer Favorites

Damage reported: minor damage



MINOR

MODERATE

SEVERE



6 Service history records



CARFAX 1-Owner vehicle



Personal vehicle



127,865 Last reported odometer reading

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/3/24 at 3:22:41 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.




Accident / Damage History


Not all accidents / issues are reported to CARFAX


Event 1

05/26/2021

Damage reported: minor damage




|  Additional History Not all accidents / issues are reported to CARFAX | Owner 1 |
|--|---|
| Total Loss No total loss reported to CARFAX. | <input checked="" type="checkbox"/> No Issues Reported |
| Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist. | <input checked="" type="checkbox"/> No Issues Reported |
| Airbag Deployment No airbag deployment reported to CARFAX. | <input checked="" type="checkbox"/> No Issues Reported |
| Odometer Check No indication of an odometer rollback. | <input checked="" type="checkbox"/> No Issues Indicated |
| Accident / Damage Damage reported: 05/26/2021. | Minor Damage |
| Manufacturer Recall Check with an authorized Subaru dealer for any open recalls. | <input checked="" type="checkbox"/> No Recalls Reported |
| Basic Warranty Original warranty estimated to have expired. | Warranty Expired |

|  Title History CARFAX guarantees the information in this section | Owner 1 |
|---|---|
| Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon | <input checked="" type="checkbox"/> Guaranteed No Problem |
| Odometer Brands Not Actual Mileage Exceeds Mechanical Limits | <input checked="" type="checkbox"/> Guaranteed No Problem |



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.
[View Terms](#) | [View Certificate](#)

|  Ownership History The number of owners is estimated | Owner 1 |
|---|----------------|
|---|----------------|

| | |
|---|-----------|
| Year purchased | 2014 |
| Type of owner | Personal |
| Estimated length of ownership | 10 years |
| Owned in the following states/provinces | New York |
| Estimated miles driven per year | 13,964/yr |
| Last reported odometer reading | 127,865 |



CARFAX Detailed History





Owner 1
Purchased: 2014






Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
13,964 mi/yr

| Date | Mileage | Source | Comments |
|------------|---------|---|--|
| 01/29/2014 | | Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ♥ 7 Customer Favorites | Vehicle offered for sale |
| 01/31/2014 | 7 | Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ♥ 7 Customer Favorites |  Vehicle serviced - Pre-delivery inspection completed |
| 03/05/2014 | 25 | Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ♥ 7 Customer Favorites |  Vehicle serviced - Safety inspection performed |
| 03/05/2014 | | New York Inspection Station | Passed safety inspection - Emissions inspection performed |
| 03/07/2014 | | Van Bortel Subaru Victor, NY | Vehicle sold |

585-924-5230
vanbortelsubaru.com
★ 4.8 / 5.0
158 Verified Reviews
♥ 7 Customer Favorites

| | | | | |
|------------|--------|---|---|--|
| 04/03/2014 | | New York Motor Vehicle Dept. Geneseo, NY | | Title issued or updated <ul style="list-style-type: none">- Registration issued or renewed- First owner reported- Titled or registered as personal vehicle- Loan or lien reported- Passed safety inspection |
| 07/17/2014 | 6,871 | Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ♥ 7 Customer Favorites |  | Vehicle serviced <ul style="list-style-type: none">- Oil and filter changed |
| 03/13/2015 | 19,962 | New York Inspection Station | | Passed safety inspection <ul style="list-style-type: none">- Emissions inspection performed |
| 02/10/2016 | | New York Motor Vehicle Dept. Geneseo, NY | | Registration issued or renewed <ul style="list-style-type: none">- Titled or registered as personal vehicle- Passed safety inspection |
| 04/08/2016 | 39,644 | New York Inspection Station | | Passed safety inspection <ul style="list-style-type: none">- Passed emissions inspection |
| 07/25/2016 | 44,885 | Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ♥ 7 Customer Favorites |  | Vehicle serviced <ul style="list-style-type: none">- Maintenance inspection completed- Oil and filter changed- Tire condition and pressure checked- Wipers/washers checked |
| 05/24/2017 | 59,698 | New York Inspection Station | | Passed safety inspection <ul style="list-style-type: none">- Passed emissions inspection |
| 01/28/2018 | | New York Motor Vehicle Dept. Geneseo, NY | | Registration issued or renewed <ul style="list-style-type: none">- Titled or registered as personal vehicle- Passed safety inspection |
| 05/25/2018 | 77,134 | New York Inspection Station | | Passed safety inspection <ul style="list-style-type: none">- Passed emissions inspection |
| 02/06/2019 | 89,928 | Van Bortel Subaru Of Rochester Rochester, NY 888-309-5502 |  | Vehicle serviced <ul style="list-style-type: none">- Inspection performed- Tire checked- Serpentine belt replaced |

vanbortelsubarurocheste
rsoa.dealer.subaru.com/

★ 4.8 / 5.0

141 Verified Reviews

♥ 15 Customer Favorites

- Battery replaced

05/16/2019 94,683

New York
Inspection Station

Passed safety inspection
- Passed emissions inspection

07/22/2019 98,272

Van Bortel Subaru Of
Rochester
Rochester, NY
888-309-5502
vanbortelsubarurocheste
rsoa.dealer.subaru.com/

★ 4.8 / 5.0

141 Verified Reviews

♥ 15 Customer Favorites



Vehicle serviced
- Lower control arm(s) replaced
- Four wheel alignment performed
- A/C refrigerant recharged

01/30/2020

New York
Motor Vehicle Dept.
Geneseo, NY

Registration issued or renewed
- Titled or registered as personal vehicle
- Passed safety inspection

05/26/2020 107,282

New York
Inspection Station

Passed safety inspection
- Passed emissions inspection

05/24/2021 114,559

New York
Inspection Station


Passed safety inspection
- Passed emissions inspection

05/26/2021

Damage Report



Damage reported: minor damage



Minor damage is usually cosmetic, including dents or scratches to the vehicle body.

03/06/2022

New York
Motor Vehicle Dept.
Geneseo, NY

Registration issued or renewed
- Titled or registered as personal vehicle
- Passed safety inspection

05/02/2022 120,441

New York
Inspection Station

Passed safety inspection
- Passed emissions inspection

05/01/2023 127,865

New York
Inspection Station

Passed safety inspection
- Passed emissions inspection

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Glossary

Damage Indicator

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/3/24 at 3:22:41 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



[facebook.com/CARFAX](https://www.facebook.com/CARFAX)



[@CARFAXinc](https://twitter.com/CARFAXinc)



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.
4/3/24 3:22:41 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2014 SUBARU XV CROSSTREK vehicle (VIN: JF2GPAGC1E8240099), which is based on information supplied to CARFAX and available as of 4/3/24 at 4:22 PM (EDT).

Customer Signature

Date

Dealer Signature

Date