



Display CARFAX in online listings:



This report provided free of charge by:
Van Bortel Ford
71 Marsh Rd
East Rochester, NY 14445
585-460-1438






5X TOP-RATED DEALER
★ **4.8 / 5.0**
1,434 Verified Reviews

♥ **9,846**
Customer Favorites




Vehicle History Report™

US \$44.99

2018 SUBARU FORESTER 2.5I VIN: JF2SJABC5JH513560 4 DOOR WAGON/SPORT UTILITY 2.5L H4 F DOHC 16V GASOLINE ALL WHEEL DRIVE This CARFAX Report Provided by: Van Bortel Ford ★ 4.8 / 5.0 1,434 Verified Reviews ♥ 9,846 Customer Favorites	Damage reported: minor damage 
	 23 Service history records
	 CARFAX 1-Owner vehicle
	 Personal vehicle
	 117,646 Last reported odometer reading

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/25/24 at 12:14:12 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.





Accident / Damage History


Not all accidents / issues are reported to CARFAX



Event 1


07/20/2018
Damage reported: minor damage

Damage Severity Scale



 Additional History Not all accidents / issues are reported to CARFAX	Owner 1
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage Damage reported: 07/20/2018.	Minor Damage
Manufacturer Recall Check with an authorized Subaru dealer for any open recalls.	<input checked="" type="checkbox"/> No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

 Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem
 GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms View Certificate	

 Ownership History The number of owners is estimated	Owner 1
Year purchased	2018
Type of owner	Personal
Estimated length of ownership	5 yrs. 9 mo.
Owned in the following states/provinces	New York
Estimated miles driven per year	20,322/yr
Last reported odometer reading	117,646





Detailed History





Owner 1

Purchased: 2018

Personal Vehicle

20,322 mi/yr

Date	Mileage	Source	Comments
01/05/2018		Five Star Subaru Oneonta, NY 607-432-0201 fivestarcars.com ★ 4.9 / 5.0 102 Verified Reviews ♥ 49 Customer Favorites	Vehicle offered for sale
01/05/2018	5	Five Star Subaru Oneonta, NY 607-432-0201 fivestarcars.com ★ 4.9 / 5.0 102 Verified Reviews ♥ 49 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed
05/15/2018		Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	Vehicle offered for sale
05/17/2018		Five Star Subaru Oneonta, NY 607-432-0201 fivestarcars.com ★ 4.9 / 5.0 102 Verified Reviews ♥ 49 Customer Favorites	Vehicle sold
05/18/2018	166	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 157 Verified Reviews ♥ 7 Customer Favorites	 Vehicle serviced - Pre-delivery inspection completed - Emissions or safety inspection performed
05/18/2018	168	New York Inspection Station	Passed safety inspection - Emissions inspection performed

05/22/2018

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

Vehicle sold

★ 4.8 / 5.0

157 Verified Reviews

♥ 7 Customer Favorites

06/18/2018

New York
Motor Vehicle Dept.
Fairport, NY

Title issued or updated

- Registration issued or renewed
- First owner reported
- Titled or registered as personal vehicle
- Loan or lien reported
- Passed safety inspection

07/20/2018

Damage Report





Damage reported: minor damage

- Damage to rear



**CARFAX HAS THE MOST
ACCIDENT & DAMAGE
INFORMATION**



Minor damage is usually cosmetic, including dents or scratches to the vehicle body.

07/30/2018 5,072


Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com



Vehicle serviced

★ 4.8 / 5.0

157 Verified Reviews


 7 Customer Favorites

08/13/2018 5,589

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

157 Verified Reviews

 7 Customer Favorites



Vehicle serviced


- Recommended maintenance performed
- Maintenance inspection completed
- Oil and filter changed
- Tire condition and pressure checked

12/17/2018 12,577

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

157 Verified Reviews

 7 Customer Favorites



Vehicle serviced


- Fluids checked
- Oil and filter changed
- Tire condition and pressure checked

04/01/2019 19,386

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

157 Verified Reviews

 7 Customer Favorites



Vehicle serviced

- Recommended maintenance performed
- Oil and filter changed
- Tire condition and pressure checked
- Emissions or safety inspection performed

04/01/2019 19,387

New York
Inspection Station

Passed safety inspection


- Emissions inspection performed

07/30/2019 30,288

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

157 Verified Reviews

 7 Customer Favorites



Vehicle serviced


- Maintenance inspection completed
- Fluids checked
- Oil and filter changed
- Tire condition and pressure checked

10/07/2019 35,769

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

157 Verified Reviews

 7 Customer Favorites



Vehicle serviced

- 30,000 mile service performed
- Fluids checked
- Oil and filter changed
- Brake fluid flushed/changed
- Tire condition and pressure checked
- Clutch fluid flushed/changed

01/23/2020 42,411

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com


 4.8 / 5.0

157 Verified Reviews



Vehicle serviced

- Maintenance inspection completed
- Brakes checked
- Rear brake pads replaced
- Rear brake rotor(s) replaced
- Brake rotor(s) replaced
- Fluids checked

 7 Customer Favorites


- Oil and filter changed
- Tire(s) balanced
- Tire condition and pressure checked
- Tires rotated

04/07/2020 46,944

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

157 Verified Reviews

 7 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Air filter replaced
- Oil and filter changed
- Tire(s) balanced
- Tires rotated
- Two tires balanced
- Tire pressure monitoring system reset

04/07/2020

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

04/30/2020

New York
Motor Vehicle Dept.
Fairport, NY

Registration issued or renewed


- Titled or registered as personal vehicle
- Passed safety inspection

09/16/2020 52,543

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

157 Verified Reviews

 7 Customer Favorites



Vehicle serviced


- Maintenance inspection completed
- Air filter replaced
- Two tires balanced
- Tires rotated
- Oil and filter changed
- Tire pressure monitoring system reset

03/29/2021 58,597

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

157 Verified Reviews

 7 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Spark plug(s) replaced
- Differential fluid flushed/changed
- Brake fluid flushed/changed
- Air filter replaced
- Two tires balanced
- Tires rotated
- Oil and filter changed
- Tire pressure monitoring system reset
- Lights checked

03/29/2021

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

08/07/2021 64,415

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

157 Verified Reviews

 7 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Wiper(s) replaced
- Tires rotated
- Oil and filter changed

12/08/2021 70,461

Van Bortel Subaru
Victor, NY



Vehicle serviced

- Maintenance inspection completed

585-924-5230
vanbortelsubaru.com
★ 4.8 / 5.0
157 Verified Reviews
❤️ 7 Customer Favorites

- Recommended maintenance performed
- Air filter replaced
- Tires rotated
- Oil and filter changed
- Air filter checked

03/25/2022 75,662

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com
★ 4.8 / 5.0
157 Verified Reviews
❤️ 7 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Tires rotated
- Oil and filter changed

03/25/2022

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

04/05/2022

New York
Motor Vehicle Dept.
Fairport, NY

Registration issued or renewed

- Titled or registered as personal vehicle
- Passed safety inspection

07/11/2022 81,132

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com
★ 4.8 / 5.0
157 Verified Reviews
❤️ 7 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Air filter replaced
- Two tires balanced
- Tires rotated
- Oil and filter changed
- Four wheel alignment performed
- Alignment performed
- Control arm(s) replaced
- Cabin air filter replaced/cleaned

10/24/2022 87,683

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com
★ 4.8 / 5.0
157 Verified Reviews
❤️ 7 Customer Favorites



Vehicle serviced

- Maintenance inspection completed
- Differential fluid flushed/changed
- Brake fluid flushed/changed
- Air filter replaced
- Two tires balanced
- Tires rotated
- Oil and filter changed
- Fog light bulb(s) replaced
- Rear brake pads replaced
- Rear brake rotor(s) replaced
- Brake rotor(s) replaced
- Tire pressure monitoring system reset
- Brakes checked


02/17/2023 93,934

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com
★ 4.8 / 5.0
157 Verified Reviews



Vehicle serviced

- Maintenance inspection completed
- Two tires balanced
- Tires rotated
- Oil and filter changed


 7 Customer Favorites

03/20/2023 95,790

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

157 Verified Reviews

 7 Customer Favorites



Vehicle serviced

03/20/2023 95,791

New York
Inspection Station

Passed safety inspection


- Passed emissions inspection

06/07/2023 100,401

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

157 Verified Reviews

 7 Customer Favorites



Vehicle serviced


- Two tires balanced
- Tires rotated
- Oil and filter changed
- Air filter replaced
- Tire pressure monitoring system reset
- Cabin air filter checked
- Cabin air filter replaced/cleaned

08/28/2023 106,321

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

157 Verified Reviews

 7 Customer Favorites



Vehicle serviced


- Oil and filter changed
- Tire condition and pressure checked

12/15/2023 112,607

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

157 Verified Reviews

 7 Customer Favorites



Vehicle serviced


- Maintenance inspection completed
- Two tires balanced
- Tires rotated
- Oil and filter changed
- Tire pressure monitoring system reset

03/04/2024 117,643

Van Bortel Subaru
Victor, NY
585-924-5230
vanbortelsubaru.com

 4.8 / 5.0

157 Verified Reviews

 7 Customer Favorites



Vehicle serviced

- Four wheel alignment performed
- Two tires balanced
- Tires rotated
- Oil and filter changed
- Alignment performed
- Tire pressure monitoring system reset
- Control arm(s) replaced
- Cabin air filter replaced/cleaned

03/04/2024 117,646

New York
Inspection Station

Passed safety inspection

- Passed emissions inspection

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Damage Indicator

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 3/25/24 at 12:14:12 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:  facebook.com/CARFAX

 [@CARFAXinc](https://twitter.com/CARFAXinc)

 [About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved.
3/25/24 12:14:12 PM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2018 SUBARU FORESTER vehicle (VIN: JF2SJABC5JH513560), which is based on information supplied to CARFAX and available as of 3/25/24 at 1:14 PM (EDT).

Customer Signature

Date

Dealer Signature

Date