Display CARFAX in online listings:



This report provided free of charge by:

Van Bortel Ford

71 Marsh Rd East Rochester, NY 14445

585-460-1438

5X TOP-RATED DEALER

 \star 4.8 / 5.0

1.438 Verified Reviews

9,894

Customer Favorites



Vehicle History Report™

US \$44.99

2014 SUBARU FORESTER 2.5I PREMIUM

VIN: JF2SJAEC5EH462885 4 DOOR WAGON/SPORT UTILITY 2.5L H4 F DOHC 16V **GASOLINE** ALL WHEEL DRIVE This CARFAX Report Provided by:

Van Bortel Ford



1,438 Verified Reviews



9,894 Customer Favorites

No accidents or damage reported to CARFAX



34 Service history records



CARFAX 1-Owner vehicle



Personal vehicle



Last owned in New York

129,289 Last reported odometer reading

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 4/3/24 at 3:21:55 PM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Additional History Not all accidents / issues are reported to CARFAX	Owner 1
Total Loss No total loss reported to CARFAX.	No Issues Reported
Structural Damage No structural damage reported to CARFAX.	No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	No Issues Reported
Odometer Check No indication of an odometer rollback.	No Issues Indicated

Accident / Damage No accidents or damage reported to CARFAX.	No Issues Reported
Manufacturer Recall Check with an authorized Subaru dealer for any open recalls.	No Recalls Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

CARFAX Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms | View Certificate

CARFAX Ownership History The number of owners is estimated	Owner 1
Year purchased	2013
Type of owner	Personal
Estimated length of ownership	10 yrs. 6 mo.
Owned in the following states/provinces	New York
Estimated miles driven per year	12,171/yr
Last reported odometer reading	129,289

CARFAX Detailed History



Owner 1 Purchased: 2013

Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle 12,171 mi/yr

Date	Mileage	Source	Comments	
08/06/2013		Van Bortel Subaru Victor, NY 585-924-5230	Vehicle offered for sale	

	vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites		
08/07/2013 7	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites	×	Vehicle serviced - Pre-delivery inspection completed - Safety inspection performed - Emissions or safety inspection performed
08/13/2013	New York Inspection Station		Passed safety inspection - Emissions inspection performed
08/14/2013	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites		Vehicle sold
09/09/2013	New York Motor Vehicle Dept. Bloomfield, NY		Title issued or updated - Registration issued or renewed - First owner reported - Titled or registered as personal vehicle - Loan or lien reported - Passed safety inspection
06/16/2014 10,628	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites	*	Vehicle serviced - Oil and filter changed - Two tires balanced - Tires rotated
08/27/2014 13,673	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites	*	Vehicle serviced - Safety inspection performed
08/27/2014	New York Inspection Station		Passed safety inspection - Passed emissions inspection
09/08/2014 14,231	Van Bortel Subaru Victor, NY	×	Vehicle serviced

		585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites		
04/10/2015		New York Motor Vehicle Dept. Bloomfield, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
06/30/2015	26,075	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites	×	Vehicle serviced - Maintenance inspection completed - Oil and filter changed
08/24/2015	28,852	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites	×	Vehicle serviced - Emissions or safety inspection performed
08/24/2015		New York		Passed safety inspection
		Inspection Station		- Emissions inspection performed
01/15/2016	34,613		*	
	34,613	Inspection Station Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews	*	- Emissions inspection performed Vehicle serviced - Oil and filter changed

08/25/2016	45,062	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites	×	Vehicle serviced
08/25/2016		New York Inspection Station		Passed safety inspection - Passed emissions inspection
11/26/2016	49,764	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites	×	Vehicle serviced - Brake light bulb(s) replaced - Oil and filter changed
04/27/2017		New York Motor Vehicle Dept. Bloomfield, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
06/08/2017	58,277	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked
08/18/2017	60,472	New York Inspection Station		Passed safety inspection - Passed emissions inspection
10/11/2017	62,124	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites	*	Vehicle serviced
12/04/2017	64,046	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - 60,000 mile service performed - Battery/charging system checked - Air filter replaced - Oil and filter changed - Brake fluid flushed/changed - Tire(s) balanced - Tire pressure sensor reprogrammed - Cabin air filter replaced/cleaned

06/19/2018	71,790	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites	*	Vehicle serviced - Oil and filter changed - Rear brake pads replaced - Rear brake rotor(s) replaced - Tire condition and pressure checked - Four tires balanced - Tires rotated
08/28/2018	75,118	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites	×	Vehicle serviced - Emissions or safety inspection performed
08/28/2018		New York Inspection Station		Passed safety inspection - Passed emissions inspection
09/12/2018	76,523	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites	×	Vehicle serviced - Air filter checked - Air filter replaced - Battery replaced - Oil and filter changed
04/02/2019		New York Motor Vehicle Dept. Bloomfield, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
05/01/2019	84,914	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites	×	Vehicle serviced - Oil and filter changed - Tire condition and pressure checked
07/08/2019	87,720	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - Wheel bearing(s)/hub(s) replaced
08/19/2019	88,646	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com	*	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked

	158 V	.8 / 5.0 erified Reviews Customer Favorites		-Emissions or safety inspection performed
08/19/2019	New Inspe	York ection Station		Passed safety inspection - Passed emissions inspection
09/30/2019 90	Victo 585-9 vanbo ★ 4. 158 V	Bortel Subaru r, NY 924-5230 ortelsubaru.com .8 / 5.0 erified Reviews Customer Favorites	×	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked
11/20/2019 92	Victo 585-9 vanbo ★ 4 158 V	Bortel Subaru r, NY 924-5230 ortelsubaru.com .8 / 5.0 erified Reviews Customer Favorites	×	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked
12/09/2019 92	Victo 585-9 vanbo ★ 4. 158 V	Bortel Subaru r, NY 924-5230 ortelsubaru.com .8 / 5.0 erified Reviews Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked
12/26/2019 93	Victo 585-9 vanbo ★ 4 158 V	Bortel Subaru r, NY 924-5230 ortelsubaru.com .8 / 5.0 erified Reviews Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Tire condition and pressure checked - Wipers/washers checked
04/24/2020 97	Victo 585-9 vanbo ★ 4. 158 V	Bortel Subaru r, NY 924-5230 ortelsubaru.com .8 / 5.0 erified Reviews Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - Front wiper blades/refills replaced - Light bulb(s) replaced
09/23/2020 98	Victo 585-9	Bortel Subaru r, NY 924-5230 ortelsubaru.com	×	Vehicle serviced - Maintenance inspection completed - Rear brakes replaced - Oil and filter changed

		★ 4.8 / 5.0158 Verified Reviews▼ 7 Customer Favorites		- Wiper(s) replaced - Rear wiper blade replaced
09/23/2020	98,763	New York Inspection Station		Passed safety inspection - Passed emissions inspection
02/15/2021	100,157	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites	×	Vehicle serviced
03/24/2021		New York Motor Vehicle Dept. Bloomfield, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
05/28/2021	101,004	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites	×	Vehicle serviced - Maintenance inspection completed - Oil and filter changed
12/18/2021	104,792	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites	×	Vehicle serviced - Maintenance inspection completed - Four wheel alignment performed - Alignment performed - Left tie rod end replaced - Tie rod(s) replaced
03/01/2022	105,835	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites	*	Vehicle serviced - Lower ball joint(s) replaced - Rear wheel bearing(s)/hub(s) replaced
03/02/2022		New York Inspection Station		Passed safety inspection - Passed emissions inspection
05/26/2022	108,066	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews	×	Vehicle serviced

		7 Customer Favorites		
03/20/2023	117,405	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites	*	Vehicle serviced - Maintenance inspection completed - Oil and filter changed - Rear brake pads replaced - Rear brake caliper(s) replaced - Front brake rotor(s) replaced - Front brake pads replaced - Ball joint(s) replaced
03/21/2023		New York Inspection Station		Passed safety inspection - Passed emissions inspection
03/23/2023		New York Motor Vehicle Dept. Bloomfield, NY		Registration issued or renewed - Titled or registered as personal vehicle - Passed safety inspection
12/06/2023	126,818	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites	×	Vehicle serviced - Air filter replaced - Drive belt(s) replaced - Oil and filter changed
03/26/2024	129,289	Van Bortel Subaru Victor, NY 585-924-5230 vanbortelsubaru.com ★ 4.8 / 5.0 158 Verified Reviews ▼ 7 Customer Favorites	×	Vehicle serviced - Emissions or safety inspection performed
03/26/2024		New York Inspection Station		Passed safety inspection - Passed emissions inspection

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.

CARFAX Glossary

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



facebook.com/CARFAX



@CARFAXinc



C About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved. 4/3/24 3:21:55 PM (CDT)

	information supplied to CARF	14 SUBARU FORESTER AX and available as of
-, = 1		